

8960 Tangnu Romai EDS dated 02.10.2015

Following shortcomings have been noticed which may be attended by the State Govt.

1. The map of the area on copy of SoI Toposheet uploaded at part I C iii and map of alternatives on SoI Toposheet uploaded at part I D is not clear. Proper map on SoI Toposheet clearly showing the alignment and other components may be uploaded.
2. Digital map of the area proposed for diversion is not proper as it does not provide detail of geo coordinates along the alignment of proposed transmission line. Geo coordinates may be mentioned on the digital map at various points along the alignment of the proposed transmission line preferably at all pole points.
3. In the cost benefit analysis various components concerning cost and benefit have not been quantified. Revised CB analysis may be sent after quantifying entries in various columns as far as possible in check list 29 Annexure B Annexure VI b and VI c.
4. Copy of SoI Toposheet indicating the boundary of the area proposed for CA not provided in column 13 iv part II.
5. In column 15 of part II date of visit of the DFO for site inspection is mentioned as 16.06.2015. However in the site inspection report attached with this column the date of site inspection is mentioned as 22.02.2014 and the site inspection report is signed dated 19.12.2014. This discrepancy may be explained.