Chaubati to Baram Bachkundi Motor Road

Objections

- 1. DFO has not uploaded the Site Inspection Report.
- 2. The recommendation file of the DFO does not show the name of the project.
- 3. The girth class wise details of trees entered in Part II is erroneous, probably confused with dia class. Kafal is entered three times.