


2030/NOC/30/E2

14 Jun 2019

Office of The District Collector  
Sriganganagar

**NO OBJECTION CERTIFICATE FOR INSTALLATION OF RETAIL OUTLET (PETROL PUMP) ON BRO ROAD BIRDHWAL-PUGAL-BAJU (KM 27.165 TO KM 27.200) AT PATHAR NO 159/43, MURBA NO 44, KILLA NO. 13/0.240, VILLAGE 10 MC, TEHSIL: SURATGARH, DIST- SRIGANGANAGAR IN THE STATE OF RAJASTHAN BY M/S INDIAN OIL CORPORATION LIMITED.**

1. Reference your letter No.F-17(1) ( ) न्याय /2015/11035-40 dated 24 Dec 2018 and letter No.F-12(3) ( ) राजस्व /2018/134 dated 11 Jan 2019.
2. On the basis of HQ Dte GBR letter No. 2180/PC/DGBR/60/TP(Pg) dated 29 Aug 2014 and MORT&H letter No. RW/NH-33023/19/99-DO-III dated 24 July 2013. **Provisional NOC** for installation of Retail Outlet (Petrol Pump) on BRO Road Birdhwa -Pugal-Baju (km 27.165 to km 27.200) at Pathar No 159/43, Mürba No 44, Killa No. 13/0.2-0, Village 10 MC, Tehsil: Suratgarh, Dist- Sriganganagar in the State of Rajasthan by M/S Indian Oil Corporation Ltd is issued. The Final approval will be given after completion of work as per approved drawings within 6 months.
3. This NOC as accorded will be null & void if:-
  - (a). Any breach of the condition/Requirement as per MORT&H letter No. RW/NH-33023/19/99/DO-III dated 24 July 2013 will happen during construction activity of Retail outlet (Petrol pump).
  - (b). The Oil company/Owner fails to construct the fuel station (Petrol Pump) along with its access as per approved drawing attached at their own cost within 6 month of the issue of **Provisional NOC**.
  - (c). The **final approval** will be issued after the construction of the fuel station (Petrol Pump) as per approved drawings and satisfaction of the BRO authorities.
  - (d). The Traffic will not be affected during construction of fuel station (Petrol Pump).
  - (e). Inspections for determining the deviations from prescribed Norms shall be done any time, even after signing of the license deed, by BRO authority. In case of defaults/deviation found during inspections by BRO authority, each deficiency shall be immediately rectified, in no case it should be exceeded 30 days from the date of inspection. The Failure to rectify the identified deficiencies within the prescribed time would lead to de-energizing the fuel station (Petrol Pump) by Indian Oil Corporation Ltd. The re-energizing would be done only on complete rectification and on the authorization by BRO authorities.
  - (f). In future or BRO work activities like widening of road all rectification/ restoration work will be done by Oil Company/Owner at their own cost.

  
(Vipin Prasad)

Major

Officer Commanding

**Copy to**

HQ 49 BRTF  
PIN- 930049  
56 APO

For info w.r.t. Office of The District Collector letter No F-17(1) G/0 ( ) न्याय /2015/11035-40 dated 24 Dec 2018 please.

