











Name of Work : Construction of Didihat - Adichaura PWD motor road to Hunera motor road (Stage - I)

	
Photograph shows starting portion at X.section no. 0/0	Photograph shows requirement of hill side cutting at X.section no. 0/5
	
Photograph shows requirement of Scupper at X.section no. 0/7 - 0/8	Photograph shows requirement of hill side cutting at X.section no. 0/12
	
Photograph shows requirement of Scupper at X.section no. 0/16 - 0/17	Photograph shows requirement of hill side cutting at X.section no. 0/20
	
Photograph shows requirement of H .P. Bend -I at X.section no. 0/24	Photograph shows requirement of hill side cutting at X.section no. 0/28
	
Photograph shows Damage Bridle Road at X.section no. 0/33	Photograph shows requirement of H .P. Bend -II at X.section no. 0/36

Handwritten signature and text in Hindi:
 नई नजारा
 नया नजारा











Handwritten signature and text in Hindi:
 वन क्षेत्राधिकारी
 पिकेट - पिथौरागढ़
 नई नजारा

Handwritten signature and text in Hindi:
 नई नजारा

A.E.R.S.
 P.L.U.-P.M.G.S.Y
 Didihat

Handwritten signature and text in Hindi:
 नई नजारा

Handwritten signature and text in Hindi:
 नई नजारा

Name of Work : Construction of Didihat - Adichaura PWD motor road to Hunera motor road (Stage - I)	
	
Photograph shows requirement of Protection at X.section no. 1/4	Photograph shows requirement of hill side cutting at X.section no. 1/8
	
Photograph shows requirement of hill side cutting at X.section no. 1/12	Photograph shows requirement of Scupper at X.section no. 1/16
	
Photograph shows requirement of hill side cutting at X.section no. 1/20	Photograph shows requirement of Scupper at X.section no. 1/24
	
Photograph shows requirement of Hill side Cutting at X.section no. 1/28	Photograph shows requirement of hill side cutting at X.section no. 1/32
	
Photograph shows requirement of Hill side Cutting at X.section no. 1/36	Photograph shows Damage Bridle Road at X.section no. 1/40

तहसीलदार
दीदीहाट बिचा रिज











वन क्षेत्राधिकारी
भुस्काट - पिथौरागढ़

Handwritten signature and initials.

A.E.R.E.S.
P.L.U. - P.M.G.S.Y
Didihat

Handwritten signature and initials.

Handwritten signature and initials.

Name of Work : Construction of Didihat - Adichaura PWD motor road to Hunera motor road (Stage - I)	
	
Photograph shows Damage Bridge Road at X.section no. 2/4	Photograph shows requirement of hill side cutting at X.section no. 2/7
	
Photograph shows Village Sunarkhet requirement of H.P. Bend -III at X.section no. 2/11- 2/12	Photograph shows requirement of Scupper at X.section no. 2/17 -2/18
	
Photograph shows requirement of Protection at X.section no. 2/21	Photograph shows requirement of Protection at X.section no. 2/24
	
Photograph shows requirement of hill Side Cutting at X.section no. 2/28	Photograph shows requirement of Scupper at X.section no. 2/31
	
Photograph shows requirement of hill side cutting at X.section no. 2/36	Photograph shows requirement of hill side cutting at X.section no. 2/40

तहसीलदार
दीदीहाट जिला पश्चिम

वन क्षेत्राधिकारी
भुस्काट - पिथौरागढ़











नरेश मंड

मुल्कादेवी
प्रधान

अ.एस.
H. J. Singh

नरेश मंड
अ.एस. / मंड

नरेश मंड
अ.एस. / मंड

Name of Work : Construction of Didihat - Adichaura PWD motor road to Hunera motor road (Stage - I)	
	
Photograph shows requirement of scupper at X.section no. 3/4 - 3/5	Photograph shows requirement of hill side cutting at X.section no. 3/8
	
Photograph shows requirement of hill side cutting at X.section no. 3/13	Photograph shows Valley Side House requirement of Seve and Side Disposat at X.section no. 3/16
	
Photograph shows requirement of scupper at X.section no. 3/19	Photograph shows requirement of scupper at X.section no. 3/24 - 3/25
	
Photograph shows requirement of 6 m span culvert X.section no. 3/30 - 3/31	Photograph shows requirement of Scupper at X.section no. 3/36
	
Photograph shows requirement of Hill Side Cutting at X.section no. 3/38	Photograph shows requirement of Scupper at X.section no. 3/40

तहसीलदार
दीदीहाट बिचा पिन











वन क्षेत्राधिकारी
प्रस्ताव - पिथौरागढ़
नरेश मास

AE

A.E.R.S.
P.L.U. - P.M.G.S.Y.
Didihat

वडाकुल

नरेश मास

Name of Work : Construction of Didihat - Adichaura PWD motor road to Hunera motor road (Stage - I)	
	
Photograph shows requirement of Scupper at X.section no. 4/3- 4/4	Photograph shows requirement of Scupper at X.section no. 4/7
	
Photograph shows requirement of Hill Side Cutting at X.section no. 4/12	Photograph shows requirement of hill side cutting at X.section no. 4/16
	
Photograph shows requirement of protection cutting at X.section no. 4/20	Photograph shows requirement of 9 m. Span minor Bridge at X.section no. 4/23 - 4/24
	
Photograph shows requirement of Scupper at X.section no. 4/25- 4/26	Photograph shows requirement of 12 m span Minor Bridge X.section no. 4/28 - 4/29
	
Photograph shows Damage Bridle Road at X.section no. 4/34- 4/37	Photograph shows Valley Side School requirement of Seve and Side Disposal at X.section no. 4/40

तहसीलदार
दीदीहाट जिला पब्लिक











वन क्षेत्राधिकारी,
भस्काट - (पिथौरागढ़)

नए 5 क

पुष्पादेवी
A.E.R.E.S.
P.U. - P.M.G.S.V

वडाहाट

नए 5 क

Name of Work : Construction of Didihat - Adichaura PWD motor road to Hunera motor road (Stage - I)	
	
Photograph shows Nap Land requirement of hill side cutting at X.section no. 5/1	Photograph shows requirement of Causeway at X.section no. 5/5
	
Photograph shows requirement of Scupper at X.section no. 5/10 - 5/11	Photograph shows requirement of hill side cutting at X.section no. 5/17
	
Photograph shows requirement of hill side cutting at X.section no. 5/20	Photograph shows requirement of Scupper at X.section no. 5/23
	
Photograph shows requirement of Scupper cutting at X.section no. 5/29	Photograph shows requirement of Protection at X.section no. 5/32
	
Photograph shows requirement of hill side cutting H. P. Bend IV at X.section no. 5/36	Photograph shows requirement of hill side cutting at X.section no. 5/40

तहसीलदार
डीडीवाड जिन्दा पिया

वन क्षेत्राधिकारी
भुस्काट - (पिथौरागढ़)

नरेश्वर

महेश्वर











ह. प्रसाद

AR

A.E.R.E.S

व. द. न. सिंह
अध्यक्ष / सरपंच

5

Name of Work : Construction of Didihat - Adichaura PWD motor road to Hunera motor road (Stage - I)	
	
Photograph shows requirement of hill side cutting at X.section no. 6/3	Photograph shows requirement of hill side cutting at X.section no. 6/8
	
Photograph shows requirement of hill side cutting at X.section no. 6/12	Photograph shows Nap Land requirement of drain at X.section no. 6/16
	
Photograph shows requirement of hill side cutting H.P. Bend - V at X.section no. 6/20	Photograph shows requirement of hill side cutting at X.section no. 6/24
	
Photograph shows requirement of drain at X.section no. 6/30	Photograph shows requirement of hill side cutting at X.section no 6/34
	
Photograph shows requirement of hill side cutting at X.section no. 6/36	Photograph shows requirement of 15 m span Bridge at X.section no. 6/39 - 6/40

तहसीलदार
दीदीहाट बिचा पिप्रा

वन क्षेत्राधिकारी
भरकाट - (पिथौरागढ़)

नरेश्वर

गज











मुख्याधिकारी
प्रधान

AE

AERES
P.I.U.-PM.G.S.Y.

नरेश्वर
अध्यक्ष/ सरपंच

नरेश्वर
अध्यक्ष/ सरपंच

Name of Work : Construction of Didihat - Adichaura PWD motor road to Hunera motor road (Stage - I)	
	
Photograph shows Vertical Clp requirement of hill side cutting at X.section no.7/4	Photograph shows E.R. requirement of hill side cutting at X.section no. 7//7
	
Photograph shows requirement of hill side cutting at X.section no. 7/12	Photograph shows requirement of hill side cutting at X.section no.7/16
	
Photograph shows requirement of hill side cutting H.P. Bend _ VI at X.section no. 7/22	Photograph shows requirement of Scupper at X.section no. 7/24
	
Photograph shows requirement of hill side cutting H.P. Bend 7 at X.section no.7/30	Photograph shows requirement of hill side cutting at X.section no.7/32
	
Photograph shows requirement of hill side cutting at X.section no.7/36	Photograph shows requirement of hill side cutting at X.section no.7/40

तहसीलदार
दीदीहाट जिला मिर्जापुर

वन क्षेत्राधिकारी,
प्रसकाट - पिथौरागढ़
नेस्ट माल

राम

AE











प्रधान
ग्राम पंचायत

A.E.R.S.
P.O. - PANGSY

वडाहाट
समय / सरपंच

57

Name of Work : Construction of Didihat - Adichaura PWD motor road to Hunera motor road (Stage - I)

	
Photograph shows requirement 9 m. Span Minor Bridge at X.section no.8/2	Photograph shows requirement of hill side cutting at X.section no.8/8
	
Photograph shows Valley Side House requirement of Seve and Side Disposal at X.section no.8/10	Photograph shows requirement of hill side cutting at X.section no. 8/16
	
Photograph shows requirement of hill side cutting at X.section no. 8/20	Photograph shows requirement of hill side cutting at X.section no. 8/24
	
Photograph shows Nap Land requirement of hill side cutting at X.section no.8/28	Photograph shows requirement of causeway at X.section no. 8/32
	
Photograph shows requirement of hill side cutting at X.section no.8/36	Photograph shows Valley Side School END Point requirement of Protection at X.section no. 8/40

तहसीलदार
दीदीहाट बिचा पिथौरागढ़

वन क्षेत्राधिकारी
अस्कार - (पिथौरागढ़)

Handwritten signature

Handwritten signature
AE

Handwritten signature

प्रधान

A.E.R.E.S.
P.L.U. - P.M.G.S.Y.

Handwritten signature

Handwritten signature
वि.क. दीदीहाट (पिथौरागढ़)