



ଓଡ଼ିଶା ଅଧିକାରୀ ତଥା ବନ୍ୟାୟନ ତତ୍ତ୍ୱାବଧାନଙ୍କ କାର୍ଯ୍ୟାଳୟ, ରାଉରକେଲା

OFFICE OF THE DIVISIONAL FOREST OFFICER CUM WILDLIFE WARDEN
ROURKELA FOREST DIVISION, ROURKELA, SUNDARGARH, ODISHA
Phone No. 0661-2664637, Fax No. 0661-2664639, e mail- dforourkela@yahoo.co.in

Memo No. 8415 / 4F (Misc.) dt. 13.12.2021

To,

The General Manager (Construction) GAIL (India) Ltd
612, Utkal Signature , Pahala, NH-5,
Bhubaneswar -752101, Odisha

Sub: -

Diversion of 0.4571 ha. of forest land coming within jurisdiction of Rourkela Forest Division for Jagadishpur-Haladia-Bokaro-Dhamara Gas Pipeline Project , (Rourkela Steel Plant Pipeline Section) by GAIL (India) Ltd.

Proposal No. FP/OR/Pipeline/147725/2021,
State Serial No: - OR-083/2021, Dt:05.10.2021

Ref:-

This office memo No.8135 dt.06.12.2021.


Sir,

With reference to this office Memo No. cited above, the undersigned had conducted site inspection on dated 10/12/2021 in your presence and forest officials of this Division and observed the following discrepancies.

- I. As per the DGPs surveyed map of the proposed forest blocks, no where RCC pillar have been irrected.
- II. GPS co-ordinates of each pillar is also not mentioned on the pillars.
- III. Sign board fixing at start and end point is also not done.

Hence, you are requested to comply the above discrepancies and report compliance to this office to take up site inspection of the project.

Yours faithfully,


13/12/21
Divisional Forest Officer,
Rourkela Division.



गेल (इंडिया) लिमिटेड
(भारत सरकार का उपक्रम - महारत्न कंपनी)
GAIL (India) Limited

(A Government of India Undertaking - A Maharatna Company)

Jagdishpur-Haldia-Bokaro-Dhamra
Gas Pipeline Project office
612, Utkal Signature, Pahala
NH-5, Bhubaneswar-752101
Phone : 0674-2972116

Ref: GAIL/JHBDPL/RSP/SPURLINE/FOREST/PERMISSION/2022/1,

Date: 14.02.2022

To,

Divisional Forest Officer,
Rourkela Forest Division
Dist: Sundargarh

Sub: Compliance of discrepancies observed during site inspection on dt. 10.12.2021 w.r.t. forest diversion proposal for Rourkela Steel Plant Spur Line under Bokaro Angul Pipeline Project

Sir,

With reference to your letter no. 8415/4F(Misc.), dt.13.12.2021, the point-wise compliance to the discrepancies is described as below:

Sl. No.	Discrepancy	Compliance Status
1.	As per the DGPS surveyed map of the proposed forest blocks, nowhere RCC pillars have been erected.	RCC pillars have been installed in forest plots as per DGPS surveyed maps.
2.	GPS co-ordinates of each pillar is also not mentioned on the pillars.	GPS co-ordinates have been mentioned on each pillar.
3.	Sign board fixing at start and end point is also not done.	GAIL Sign board fixing done at start and end point.

This is for your kind consideration and needful action.

Thanking you,

Yours Sincerely,

S.K. Mandal 14.02.2022

Subrat Kumar Mandal
Sr. Manager, GAIL(India)Ltd.

Received
R 14/2/22
H/K

पंजीकृत कार्यालय: _____