

ब्रिडकुल-पी०एम०जी०एस०वाई० पी0आई0य्0, गैरसैंण

ब्रिज, रोपवे, टनल एण्ड अदर इन्फ्रास्ट्रक्चर डेवलपमेंट कॉरपोरेषन ऑफ उत्तराखण्ड लिमिटेड (उत्तराखण्ड सरकार का उपक्रम)

प्रधानमंत्री ग्राम सङ्क योजना

पी0आई0यू० कार्यालय.—नीयर स्टैट बैंक ऑफ इण्डीया, पॉ0ऑ० सिमली, कर्णप्रयाग, जिला चमोली—246474



पंत्राक 32 /ब्रिडकुल / पी०एम०जी०एस०वाई० (गैरसँण) - 12 44/21 दिनांक 22 / निकी / 2021

To,

The Nodal Office,

IndiraNagar Forest Colony

Dehradun, UK

Sub:

Regarding Taituda to Naini Motor Road under PMGSY Motor Road Proposal No.

FP/UK/ROAD/50196/2020

Ref: EDS file No. Nodal 25-03-2021

Dear sir,

In reference to above mentioned letter the shotcoming has been shorted by User Agency which

is given below:-

S. no.	Queries	Resolves
1.	CA Area KML file is not found uploaded in Part-I as well as Part-II. Kindly upload the KML File of the CA area to relevent place.	Post-2
2.	Extra distance from the Kedarnath Wile Life Sanctury not Mentained in the Aerial Distrance Certificate. Kindly Maintained the same.	April clustere from the Kedarnath Wild Life Sanctury Mentained in the Aerial Distrance Certificate is uploaded. additional Information part-I
3.	There is difference in the number of trees effected of the trees list uploaded and but maintained in the part-II 4 (II) also there is difference in number of Banj trees, these list as well as what maintained in the recommendation of CF and the cost of trees list.	Consection has been made
4.	Check list & Fact List not uploaded in Part-I	Check list & Fact List uploaded in Part-I and Hardcopy is sending in Nodal Office.

परियोजना प्रबन्धक (गा०बाई०वु०) पीर्णगण्जीर्पराठवाईर, बिडकूत asotel Garrosei