

इकाई कार्यालय: उप परियोजना प्रबन्धक  
उ० प्र० राज्य सेतु निगम लि०  
सेतु निर्माण इकाई,—  
निकट भावना टावर,  
रेल उपरिगामी सेतु-502,  
गुरु का ताल-हरी पर्वत मार्ग,  
आगरा (यू०पी०)  
पिन कोड नं०-282007  
GST NO. 09AAACU3258KSZA



Office of The **Dy. Project Manager**  
U.P.STATE BRIDGE CORPORATION LTD.  
BRIDGE CONSTRUCTION UNIT-  
Near Bhawana Tower,  
Railway Over Bridge-502  
Guru Ka Tal-Hari Parvat Marg,  
Agra. (U.P.) Pin Code No. 282007  
E-mail- upsbc.bcu1agra@gmail.com  
CIN-U45203UP1972SGC003623

Letter No. ENGG./ DFO/02/03

Dated: 09.05.2023

To,  
The Divisional Forest Officer  
Social Forest Division  
Agra


**Subject :** Diversion of 0.0730 Hec. Protected Forest Land (0.0113 Hec. Of Protected Forest Land At Nh-11,Chainage 9.94 In Village-Laramada & 0.0617 Hec. Of Protected Forest Land On L.H.S At Agra Terminal Distributory Canal Chainage Mile 11.0 In Village- Nagla Basua For Construction Of 4-Lane R.O.B At Level X-Ing No. 68b/2e At Km 73/7-8 In Idgah-Bayana Rail Section On Runakata To Rohta Road In Dist-Agra (U.P)

**MOEE&F Reference Letter No.- 8B/U.P/06/144/2022/F.C/47 Dated 20.04.2023**

Dear Sir,

Please take above reference. Our reply are given below:-

Sr. No.	Observation	Reply
1	Positional error has been found in the Geo-referenced map which has yet not been rectified. Geo-referenced map of the area proposed for diversion needs rectification.	Revised GPS map and KML uploaded on MOEF&CC Portal.
2	With Respect to violation,date of violation,extent of violation and all necessary action in this regard taken by the State Govt. need to be submitted in this office. Also, violation in this case was reported only after it was observed by Regional office. Why was it not reported by the DFO earlier?	It is in Scope of DFO Agra.

  
(Anoop M.L. Sharma)  
(Anoop M.L. Sharma)  
Junior Engineer  
Junior Engineer (Civil),  
BRIDGE CONSTRUCTION UNIT  
AGRA