

Registered Post

101 Road Constr Coy (GREF)

C/O 56 APO

Pin-930101

2030/NOC/ 74 /E2

83 Feb 2021

Office of The District Collector and
District Magistrate
Sriganganagar

NO OBJECTION CERTIFICATE FOR INSTALLATION OF RETAIL OUTLET (PETROL PUMP) ON BRO ROAD BIRHWAL-PUGAL-BAJJU AT KM 46.05, RHS MURABBA NO. 19, PATTHAR NO. 4/37, KILLA NO. 23, VILLAGE 2 DOB, TEHSIL: SURATGARH, DIST- SRIGANGANAGAR IN THE STATE OF RAJASTHAN BY M/S HINDUSTAN PETROLEUM CORPORATION LIMITED.

1. Reference your letter No. F17 (I) () न्याय/2020/20114-20120 dated 30 Sep 2020.
2. On the basis of HQ Dte GBR letter No. 2180/PC/ DGBR/60/TP(Plg) dated 29 Aug 2014 and MORT&H letter No. RW/NH-33023/19/99-DO-III dated 24 July 2013, **Provisional NOC** for installation of Retail Outlet (Petrol Pump) on BRO Road Birdhwal-Pugal-Bajju at Km 46.05 RHS at Murabba No. 19, Patthar No. 4/37, Killa No. 23, Village 2 DOB, Tehsil: Suratgarh, Dist- Sriganganagar in the State of Rajasthan By M/S Hindustan Petroleum Corporation Limited is issued. The Final approval will be given after completion of work as per approved drawings within 6 months.
3. This NOC as accorded will be null & void if:-
 - (a) Any breach of the condition/Requirement as per MORT&H letter No. RW/NH-33023/19/99-DO-III dated 24 July 2013 will happen during construction activity of Retail outlet (Petrol Pump).
 - (b) The oil company/Owner fails to construct the fuel station (Petrol Pump) along with its access as per approved drawing attached at their own cost within 6 month of the issue of **Provisional NOC**.
 - (c) The **final approval** will be issued after the construction of the fuel station (Petrol Pump) as per approved drawings and satisfaction of the BRO authorities.
 - (d) The Traffic will not be affected during construction of fuel station (Petrol Pump).
 - (e) Inspections for determining the deviations from prescribed Norms shall be done any time, even after signing of the license deed, by BRO authority. In case of defaults/deviation found during inspections by BRO authority, each deficiency shall be immediately rectified, in no case it should be exceeded 30 days from the date of inspection. The Failure to rectify the identified deficiencies within the prescribed time would lead to de-energizing the fuel station (Petrol Pump) by Hindustan Petroleum Corporation Limited. The re-energizing would be done only on complete rectification and on the authorization by BRO authorities.
 - (f) In future for BRO work activities like widening of road, all rectification/ restoration work will be done by Oil Company / Owner at their own cost.

(Vipin Prasad)

Major

Officer Commanding

Copy to :-

1. HQ 49 BRTF (GREF)
Pin - 930049
C/o 56 APO

: For info w.r.t. Office of The District Collector and
District Magistrate letter No. F17 (I) ()
न्याय/2020/20114-20120 dated 30 Sep 2020.