

**Name of Work:-" Detailed Project Report (DPR) for Two laning of Hukanjuri to Khonsa road  
section of NH-315A in the state of Arunachal Pradesh"**

**CD INVENTORY**

| SL No | Existing |       |                        | Proposed |             |                  |
|-------|----------|-------|------------------------|----------|-------------|------------------|
|       | Chainage | Size  | Ramarks/condition      | Chainage | Size        | Remarks          |
| 1     | 20.0     | 1x2x2 | Damaged (Slab Culvert) | 20.0     | 1x2x2       | Box Cell Culvert |
| 2     | 205.0    | 1x2x2 | Damaged (Slab Culvert) | 205.0    | 1x2x2       | Box Cell Culvert |
| 3     | 310      | 1x2x2 | Damaged (Slab Culvert) | 360.0    | 1x2x2       | Box Cell Culvert |
| 4     | 525      | 1x2x2 | Damaged (Slab Culvert) | 520.0    | 1x2x2       | Box Cell Culvert |
| 5     | 825      | 1x2x2 | Damaged (Slab Culvert) | 795.0    | 1x2x2       | Box Cell Culvert |
| 6     | 955      | 1x2x2 | Damaged (Slab Culvert) | 920.0    | 1x2x2       | Box Cell Culvert |
| 7     | 1060     | 1x2x2 | Damaged (Slab Culvert) | 1025.0   | 1x2x2       | Box Cell Culvert |
| 8     | 1510     | 1x2x2 | Damaged (Slab Culvert) | 1470.0   | 1x2x2       | Box Cell Culvert |
| 9     | 1690     | 1x2x2 | Damaged (Slab Culvert) | 1630.0   | 1x3x3       | Box Cell Culvert |
| 10    | 1990     | 1x2x2 | Damaged (Slab Culvert) | 1925.0   | 1x4x4       | Box Cell Culvert |
| 11    | 2310     | 1x2x2 | Damaged (Slab Culvert) | 2245.0   | 1x2x2       | Box Cell Culvert |
| 12    | 2660     | 1x2x2 | Damaged (Slab Culvert) | 2600.0   | 1x2x2       | Box Cell Culvert |
| 13    | 2925     | 2x12m | Damaged (Slab Culvert) | 2850.0   | 2x12m       | Bridge           |
| 14    | NIL      | NIL   | New                    | 2950.0   | 1x3x3       | Box Cell Culvert |
| 15    | 3400     | 1x2x2 | Damaged (Slab Culvert) | 3125.0   | 1x2x2       | Box Cell Culvert |
| 16    | 3240     | 1x2x2 | Damaged (Slab Culvert) | 3270.0   | 1x2x2       | Box Cell Culvert |
| 17    | 3850     | 1x2x2 | Damaged (Slab Culvert) | 3575.0   | 1x2x2       | Box Cell Culvert |
| 18    | NIL      | NIL   | New                    | 3903.0   | 1x2x2       | Box Cell Culvert |
| 19    | NIL      | NIL   | New                    | 3990.0   | 1x3x3       | Box Cell Culvert |
| 20    | NIL      | NIL   | New                    | 4035.0   | 1x4x4       | Box Cell Culvert |
| 21    | 4770     | 1x2x2 | Damaged (Slab Culvert) | 4145.0   | 1x3x3       | Box Cell Culvert |
| 22    | 5020     | 1x2x2 | Damaged (Slab Culvert) | 4380.0   | 1x2x2       | Box Cell Culvert |
| 23    | NIL      | NIL   | New                    | 4480.0   | 1x2x2       | Box Cell Culvert |
| 24    | 5220     | 1x2x2 | Damaged (Slab Culvert) | 4585.0   | 1x4x4       | Box Cell Culvert |
| 25    | NIL      | NIL   | New                    | 4720.0   | 1x2x2       | Box Cell Culvert |
| 26    | 5500     | 1x2x2 | Damaged (Slab Culvert) | 4855.0   | 1x5x5       | Box Cell Culvert |
| 27    | 6075     | 1x2x2 | Damaged (Slab Culvert) | 5420.0   | 1x4x4       | Box Cell Culvert |
| 28    | 6190     | 1x2x2 | Damaged (Slab Culvert) | 5520.0   | 1x4x4       | Box Cell Culvert |
| 29    | 6300     | 1x2x2 | Damaged (Slab Culvert) | 5620.0   | 1x3x3       | Box Cell Culvert |
| 30    | 6475     | 1x2x2 | Damaged (Slab Culvert) | 5780.0   | 1x3x3       | Box Cell Culvert |
| 31    | NIL      | NIL   | New                    | 5950.0   | 1x2x2       | Box Cell Culvert |
| 32    | 6810     | 1x2x2 | Damaged (Slab Culvert) | 6110.0   | 1x3x3       | Box Cell Culvert |
| 33    | 6955     | 1x2x2 | Damaged (Slab Culvert) | 6250.0   | 1x2x2       | Box Cell Culvert |
| 34    | NIL      | NIL   | New                    | 6330.0   | 1x2x2       | Box Cell Culvert |
| 35    | NIL      | NIL   | New                    | 6420.0   | 1x2x2       | Box Cell Culvert |
| 36    | NIL      | NIL   | New                    | 6450.0   | 1x3x3       | Box Cell Culvert |
| 37    | NIL      | NIL   | New                    | 6670.0   | 1x3x3       | Box Cell Culvert |
| 38    | 7590     | 1x2x2 | Damaged (Slab Culvert) | 6723.0   | 1x2x2       | Box Cell Culvert |
| 39    | NIL      | NIL   | New                    | 7020.0   | 1x3x3       | Box Cell Culvert |
| 40    | 8025     | 1x2x2 | Damaged (Slab Culvert) | 7145.0   | 1x3x3       | Box Cell Culvert |
| 41    | NIL      | NIL   | New                    | 7210.0   | 1x2x2       | Box Cell Culvert |
| 42    | 8175     | 1x2x2 | Damaged (Slab Culvert) | 7285.0   | 1x4x4       | Box Cell Culvert |
| 43    | NIL      | NIL   | New                    | 7435.0   | 1x5x5       | Box Cell Culvert |
| 44    | 8490     | 1x2x2 | Damaged (Slab Culvert) | 7585.0   | 1x4x4       | Box Cell Culvert |
| 45    | NIL      | NIL   | New                    | 7700.0   | (2x10+2x24) | Bridge           |



| Culvert & Bridge Details of Hukanjuri - Khonsa Road (NH-315A) |          |        |                        |          |             |                  |
|---------------------------------------------------------------|----------|--------|------------------------|----------|-------------|------------------|
| SL No                                                         | Existing |        |                        | Proposed |             |                  |
|                                                               | Chainage | Size   | Ramarks/condition      | Chainage | Size        | Remarks          |
| 46                                                            | NIL      | NIL    | New                    | 7810.0   | 1x4x4       | Box Cell Culvert |
| 47                                                            | 9580     | 1x2x2  | Damaged (Slab Culvert) | 7955.0   | 1x2x2       | Box Cell Culvert |
| 48                                                            | 9660     | 1x2x2  | Damaged (Slab Culvert) | 8035.0   | 1x2x2       | Box Cell Culvert |
| 49                                                            | 9800     | 1x2x2  | Damaged (Slab Culvert) | 8160.0   | 1x2x2       | Box Cell Culvert |
| 50                                                            | 9920     | 1x2x2  | Damaged (Slab Culvert) | 8260.0   | 1x2x2       | Box Cell Culvert |
| 51                                                            | NIL      | NIL    | New                    | 8425.0   | 1x2x2       | Box Cell Culvert |
| 52                                                            | NIL      | NIL    | New                    | 8678.0   | 1x4x4       | Box Cell Culvert |
| 53                                                            | NIL      | NIL    | New                    | 8785.0   | 1x4x4       | Box Cell Culvert |
| 54                                                            | 1530     | 1x2x2  | Damaged (Slab Culvert) | 8885.0   | 1x2x2       | Box Cell Culvert |
| 55                                                            | NIL      | NIL    | New                    | 9000.0   | 1x2x2       | Box Cell Culvert |
| 56                                                            | NIL      | NIL    | New                    | 9100.0   | 1x24m       | Bridge           |
| 57                                                            | 1870     | 1x2x2  | Damaged (Slab Culvert) | 9150.0   | 1x2x2       | Box Cell Culvert |
| 58                                                            | NIL      | NIL    | New                    | 9220.0   | 1x2x2       | Box Cell Culvert |
| 59                                                            | NIL      | NIL    | New                    | 9285.0   | 1x2x2       | Box Cell Culvert |
| 60                                                            | NIL      | NIL    | New                    | 9360.0   | 1x5x5       | Box Cell Culvert |
| 61                                                            | NIL      | NIL    | New                    | 9478.0   | 1x3x3       | Box Cell Culvert |
| 62                                                            | NIL      | NIL    | New                    | 9575.0   | 1x3x3       | Box Cell Culvert |
| 63                                                            | NIL      | NIL    | New                    | 9720.0   | 1x2x2       | Box Cell Culvert |
| 64                                                            | 12025    | 1x2x2  | Damaged (Slab Culvert) | 9800.0   | 1x3x3       | Box Cell Culvert |
| 65                                                            | 12150    | 1x2x2  | Damaged (Slab Culvert) | 9925.0   | 1x2x2       | Box Cell Culvert |
| 66                                                            | NIL      | NIL    | New                    | 10040.0  | 1x2x2       | Box Cell Culvert |
| 67                                                            | 12460    | 1x2x2  | Damaged (Slab Culvert) | 10200.0  | 1x2x2       | Box Cell Culvert |
| 68                                                            | NIL      | NIL    | New                    | 10350.0  | (2x10+1x24) | Bridge           |
| 69                                                            | NIL      | NIL    | New                    | 10390.0  | 1x2x2       | Box Cell Culvert |
| 70                                                            | 12900    | 1x8x5  | Damaged (Slab Culvert) | 10590.0  | 1x8x5       | Box Cell Culvert |
| 71                                                            | 13175    | 1x2x2  | Damaged (Slab Culvert) | 10865.0  | 1x2x2       | Box Cell Culvert |
| 72                                                            | 13320    | 1x2x2  | Damaged (Slab Culvert) | 11005.0  | 1x2x2       | Box Cell Culvert |
| 73                                                            | NIL      | NIL    | New                    | 11105.0  | 1x2x2       | Box Cell Culvert |
| 74                                                            | NIL      | NIL    | New                    | 11255.0  | 1x5x5       | Box Cell Culvert |
| 75                                                            | 13840    | 1x2x2  | Damaged (Slab Culvert) | 11510.0  | 1x2x2       | Box Cell Culvert |
| 76                                                            | 13990    | 1x2x2  | Damaged (Slab Culvert) | 11660.0  | 1x2x2       | Box Cell Culvert |
| 77                                                            | NIL      | NIL    | New                    | 11780.0  | 1x4x4       | Box Cell Culvert |
| 78                                                            | NIL      | NIL    | New                    | 11845.0  | 1x2x2       | Box Cell Culvert |
| 79                                                            | NIL      | NIL    | New                    | 12075.0  | 1x2x2       | Box Cell Culvert |
| 80                                                            | NIL      | NIL    | New                    | 12220.0  | 1x3x3       | Box Cell Culvert |
| 81                                                            | NIL      | NIL    | New                    | 12260.0  | 1x2x2       | Box Cell Culvert |
| 82                                                            | NIL      | NIL    | New                    | 12460.0  | 1x2x2       | Box Cell Culvert |
| 83                                                            | NIL      | NIL    | New                    | 12525.0  | 1x2x2       | Box Cell Culvert |
| 84                                                            | NIL      | NIL    | New                    | 12720.0  | 1x2x2       | Box Cell Culvert |
| 85                                                            | NIL      | NIL    | New                    | 12830.0  | 1x2x2       | Box Cell Culvert |
| 86                                                            | 15410    | 1x2x2  | Damaged (Slab Culvert) | 12960.0  | 1x2x2       | Box Cell Culvert |
| 87                                                            | NIL      | NIL    | New                    | 13000.0  | (1x24+2x21) | Bridge           |
| 88                                                            | NIL      | NIL    | New                    | 13130.0  | 1x2x2       | Box Cell Culvert |
| 89                                                            | 16225    | 2x16x5 | Damaged (Slab Culvert) | 13450.0  | 2x16m       | Bridge           |
| 90                                                            | 16395    | 1x2x2  | Damaged (Slab Culvert) | 13600.0  | 1x3x3       | Box Cell Culvert |




| Culvert & Bridge Details of Hukanjuri - Khonsa Road (NH-315A) |          |       |                        |          |       |                  |
|---------------------------------------------------------------|----------|-------|------------------------|----------|-------|------------------|
| SL No                                                         | Existing |       |                        | Proposed |       |                  |
|                                                               | Chainage | Size  | Ramarks/condition      | Chainage | Size  | Remarks          |
| 91                                                            | NIL      | NIL   | New                    | 13855.0  | 1x4x4 | Box Cell Culvert |
| 92                                                            | NIL      | NIL   | New                    | 14000.0  | 1x3x3 | Box Cell Culvert |
| 93                                                            | 16870    | 1x2x2 | Damaged (Slab Culvert) | 14060.0  | 1x2x2 | Box Cell Culvert |
| 94                                                            | NIL      | NIL   | New                    | 14090.0  | 1x2x2 | Box Cell Culvert |
| 95                                                            | 17080    | 1x2x2 | Damaged (Slab Culvert) | 14245.0  | 1x2x2 | Box Cell Culvert |
| 96                                                            | NIL      | NIL   | New                    | 14425.0  | 1x3x3 | Box Cell Culvert |
| 97                                                            | NIL      | NIL   | New                    | 14595.0  | 1x3x3 | Box Cell Culvert |
| 98                                                            | NIL      | NIL   | New                    | 14690.0  | 1x4x4 | Box Cell Culvert |
| 99                                                            | NIL      | NIL   | New                    | 14815.0  | 1x4x4 | Box Cell Culvert |
| 100                                                           | NIL      | NIL   | New                    | 14900.0  | 1x3x3 | Box Cell Culvert |
| 101                                                           | NIL      | NIL   | New                    | 15100.0  | 1x4x4 | Box Cell Culvert |
| 102                                                           | NIL      | NIL   | New                    | 15375.0  | 1x3x3 | Box Cell Culvert |
| 103                                                           | NIL      | NIL   | New                    | 15605.0  | 1x5x5 | Box Cell Culvert |
| 104                                                           | NIL      | NIL   | New                    | 15850.0  | 3x24  | Bridge           |
| 105                                                           | NIL      | NIL   | New                    | 15910.0  | 1x4x4 | Box Cell Culvert |
| 106                                                           | NIL      | NIL   | New                    | 16025.0  | 1x2x2 | Box Cell Culvert |
| 107                                                           | NIL      | NIL   | New                    | 16250.0  | 1x2x2 | Box Cell Culvert |
| 108                                                           | 20455    | 1x2x2 | Damaged (Slab Culvert) | 16430.0  | 1x3x3 | Box Cell Culvert |
| 109                                                           | NIL      | NIL   | New                    | 16620.0  | 1x3x3 | Box Cell Culvert |
| 110                                                           | NIL      | NIL   | New                    | 17195.0  | 1x2x2 | Box Cell Culvert |
| 111                                                           | NIL      | NIL   | New                    | 17425.0  | 1x2x2 | Box Cell Culvert |
| 112                                                           | NIL      | NIL   | New                    | 17610.0  | 1x2x2 | Box Cell Culvert |
| 113                                                           | NIL      | NIL   | New                    | 17820.0  | 1x2x2 | Box Cell Culvert |
| 114                                                           | NIL      | NIL   | New                    | 17955.0  | 1x3x3 | Box Cell Culvert |
| 115                                                           | NIL      | NIL   | New                    | 18090.0  | 1x2x2 | Box Cell Culvert |
| 116                                                           | NIL      | NIL   | New                    | 18155.0  | 1x2x2 | Box Cell Culvert |
| 117                                                           | NIL      | NIL   | New                    | 18550.0  | 1x2x2 | Box Cell Culvert |
| 118                                                           | NIL      | NIL   | New                    | 11665.0  | 1x3x3 | Box Cell Culvert |
| 119                                                           | NIL      | NIL   | New                    | 18825.0  | 1x2x2 | Box Cell Culvert |
| 120                                                           | NIL      | NIL   | New                    | 19075.0  | 1x3x3 | Box Cell Culvert |
| 121                                                           | 24225    | 1x2x2 | Damaged (Slab Culvert) | 19395.0  | 1x2x2 | Box Cell Culvert |
| 122                                                           | NIL      | NIL   | New                    | 19460.0  | 1x2x2 | Box Cell Culvert |
| 123                                                           | NIL      | NIL   | New                    | 19960.0  | 1x2x2 | Box Cell Culvert |
| 124                                                           | NIL      | NIL   | New                    | 20015.0  | 1x3x3 | Box Cell Culvert |
| 125                                                           | 25000    | 1x2x2 | Damaged (Slab Culvert) | 20115.0  | 1x2x2 | Box Cell Culvert |
| 126                                                           | NIL      | NIL   | New                    | 22245.0  | 1x4x4 | Box Cell Culvert |
| 127                                                           | NIL      | NIL   | New                    | 20465.0  | 1x3x3 | Box Cell Culvert |
| 128                                                           | NIL      | NIL   | New                    | 20695.0  | 1x2x2 | Box Cell Culvert |
| 129                                                           | NIL      | NIL   | New                    | 20780.0  | 1x3x3 | Box Cell Culvert |
| 130                                                           | NIL      | NIL   | New                    | 21000.0  | 1x2x2 | Box Cell Culvert |
| 131                                                           | 26440    | 1x2x2 | Damaged (Slab Culvert) | 21215.0  | 1x4x4 | Box Cell Culvert |
| 132                                                           | NIL      | NIL   | New                    | 21395.0  | 1x2x2 | Box Cell Culvert |
| 133                                                           | 26945    | 1x2x2 | Damaged (Slab Culvert) | 21645.0  | 1x2x2 | Box Cell Culvert |
| 134                                                           | NIL      | NIL   | New                    | 21830.0  | 1x2x2 | Box Cell Culvert |
| 135                                                           | NIL      | NIL   | New                    | 21925.0  | 1x2x2 | Box Cell Culvert |

| Culvert & Bridge Details of Hukanjuri - Khonsa Road (NH-315A) |          |       |                        |          |       |                  |
|---------------------------------------------------------------|----------|-------|------------------------|----------|-------|------------------|
| SL No                                                         | Existing |       |                        | Proposed |       |                  |
|                                                               | Chainage | Size  | Ramarks/condition      | Chainage | Size  | Remarks          |
| 136                                                           | 27290    | 1x2x2 | Damaged (Slab Culvert) | 21990.0  | 1x2x2 | Box Cell Culvert |
| 137                                                           | 27575    | 1x2x2 | Damaged (Slab Culvert) | 22225.0  | 1x2x2 | Box Cell Culvert |
| 138                                                           | 27750    | 1x2x2 | Damaged (Slab Culvert) | 22420.0  | 1x2x2 | Box Cell Culvert |
| 139                                                           | 27800    | 1x2x2 | Damaged (Slab Culvert) | 22470.0  | 1x2x2 | Box Cell Culvert |
| 140                                                           | 27960    | 1x2x2 | Damaged (Slab Culvert) | 22595.0  | 1x2x2 | Box Cell Culvert |
| 141                                                           | NIL      | NIL   | New                    | 22740.0  | 1x4x4 | Box Cell Culvert |
| 142                                                           | NIL      | NIL   | New                    | 22905.0  | 1x2x2 | Box Cell Culvert |
| 143                                                           | NIL      | NIL   | New                    | 23000.0  | 1x3x3 | Box Cell Culvert |
| 144                                                           | 28900    | 1x2x2 | Damaged (Slab Culvert) | 23085.0  | 1x2x2 | Box Cell Culvert |
| 145                                                           | NIL      | NIL   | New                    | 23270.0  | 1x2x2 | Box Cell Culvert |
| 146                                                           | 29290    | 1x2x2 | Damaged (Slab Culvert) | 23435.0  | 1x2x2 | Box Cell Culvert |
| 147                                                           | NIL      | NIL   | New                    | 23680.0  | 1x3x3 | Box Cell Culvert |
| 148                                                           | NIL      | NIL   | New                    | 23945.0  | 1x3x3 | Box Cell Culvert |
| 149                                                           | NIL      | NIL   | New                    | 24240.0  | 1x2x2 | Box Cell Culvert |
| 150                                                           | NIL      | NIL   | New                    | 24405.0  | 1x4x4 | Box Cell Culvert |
| 151                                                           | NIL      | NIL   | New                    | 24555.0  | 1x3x3 | Box Cell Culvert |
| 152                                                           | NIL      | NIL   | New                    | 24700.0  | 1x5x5 | Box Cell Culvert |
| 153                                                           | 31000    | 1x2x2 | Damaged (Slab Culvert) | 24865.0  | 1x4x4 | Box Cell Culvert |
| 154                                                           | NIL      | NIL   | New                    | 25110.0  | 1x2x2 | Box Cell Culvert |
| 155                                                           | 31540    | 1x2x2 | Damaged (Slab Culvert) | 25365.0  | 1x3x3 | Box Cell Culvert |
| 156                                                           | NIL      | NIL   | New                    | 25455.0  | 1x2x2 | Box Cell Culvert |
| 157                                                           | NIL      | NIL   | New                    | 25660.0  | 1x24m | Bridge           |
| 158                                                           | 32155    | 1x2x2 | Damaged (Slab Culvert) | 25875.0  | 1x2x2 | Box Cell Culvert |
| 159                                                           | 32290    | 1x2x2 | Damaged (Slab Culvert) | 26015.0  | 1x3x3 | Box Cell Culvert |
| 160                                                           | 32380    | 1x2x2 | Damaged (Slab Culvert) | 26110.0  | 1x2x2 | Box Cell Culvert |
| 161                                                           | NIL      | NIL   | New                    | 26400.0  | 1x2x2 | Box Cell Culvert |
| 162                                                           | 32960    | 1x2x2 | Damaged (Slab Culvert) | 26675.0  | 1x3x3 | Box Cell Culvert |
| 163                                                           | 33150    | 1x2x2 | Damaged (Slab Culvert) | 26865.0  | 1x2x2 | Box Cell Culvert |
| 164                                                           | 33370    | 1x2x2 | Damaged (Slab Culvert) | 27070.0  | 1x2x2 | Box Cell Culvert |
| 165                                                           | 33575    | 1x2x2 | Damaged (Slab Culvert) | 27270.0  | 1x2x2 | Box Cell Culvert |
| 166                                                           | 33770    | 1x3x3 | Damaged (Slab Culvert) | 27470.0  | 1x3x3 | Box Cell Culvert |

  
**Executive Engineer**  
 Khonsa Highway Division  
 PWD, Khonsa



| Retainning Wall Details of Hukanjuri - Khonsa Road (NH-315A) |              |            |               |           |
|--------------------------------------------------------------|--------------|------------|---------------|-----------|
| SL No                                                        | Starting Chn | Ending Chn | Total         | Remark    |
| 1                                                            | 5500.000     | 5550.000   | 50.0          | RHS       |
| 2                                                            | 6950.000     | 6990.000   | 40.0          | RHS       |
| 3                                                            | 7650.000     | 7670.000   | 40.0          | BOTH SIDE |
| 4                                                            | 7730.000     | 7750.000   | 40.0          | BOTH SIDE |
| 5                                                            | 8100.000     | 8175.000   | 75.0          | RHS       |
| 6                                                            | 8980.000     | 9020.000   | 40.0          | RHS       |
| 7                                                            | 9070.000     | 9080.000   | 20.0          | BOTH SIDE |
| 8                                                            | 9105.000     | 9120.000   | 30.0          | BOTH SIDE |
| 9                                                            | 10310.000    | 10330.000  | 40.0          | BOTH SIDE |
| 10                                                           | 10360.000    | 10380.000  | 40.0          | BOTH SIDE |
| 11                                                           | 11180.000    | 11300.000  | 120.0         | RHS       |
| 12                                                           | 12050.000    | 12120.000  | 70.0          | RHS       |
| 13                                                           | 14420.000    | 14470.000  | 100.0         | BOTH SIDE |
| 14                                                           | 12960.000    | 12980.000  | 40.0          | BOTH SIDE |
| 15                                                           | 13040.000    | 13060.000  | 40.0          | BOTH SIDE |
| 16                                                           | 15200.000    | 15320.000  | 120.0         | RHS       |
| 17                                                           | 15780.000    | 15820.000  | 80.0          | BOTH SIDE |
| 18                                                           | 15880.000    | 15900.000  | 40.0          | BOTH SIDE |
| 19                                                           | 20225.000    | 20270.000  | 90.0          | BOTH SIDE |
| 20                                                           | 20450.000    | 20470.000  | 40.0          | BOTH SIDE |
| 21                                                           | 23830.000    | 24200.000  | 370.0         | RHS       |
| 22                                                           | 25630.000    | 25645.000  | 30.0          | BOTH SIDE |
| 23                                                           | 25685.000    | 25710.000  | 25.0          | LHS       |
| 24                                                           | 25685.000    | 25800.000  | 115.0         | RHS       |
| 25                                                           | 26220.000    | 27090.000  | 870.0         | LHS       |
| 26                                                           | 26220.000    | 26300.000  | 80.0          | RHS       |
|                                                              |              |            | <b>2645.0</b> |           |

  
 Executive Engineer  
 Khonsa Highway Division  
 PWD, Khonsa

### Breast Wall Details of Hukanjuri - Khonsa Road (NH-315A)

| SL No | St Chn    | End Chn   | Total          | Remark    |
|-------|-----------|-----------|----------------|-----------|
| 1     | 3900.000  | 3950.000  | 100.0          | BOTH SIDE |
| 2     | 3970.000  | 4070.000  | 200.0          | BOTH SIDE |
| 3     | 4400.000  | 4500.000  | 200.0          | BOTH SIDE |
| 4     | 4900.000  | 5000.000  | 100.0          | LHS       |
| 5     | 5060.000  | 5250.000  | 190.0          | LHS       |
| 6     | 5320.000  | 5470.000  | 150.0          | LHS       |
| 7     | 5650.000  | 5750.000  | 200.0          | BOTH SIDE |
| 8     | 5800.000  | 5900.000  | 100.0          | LHS       |
| 9     | 6300.000  | 6675.000  | 375.0          | LHS       |
| 10    | 6300.000  | 6575.000  | 275.0          | RHS       |
| 11    | 7450.000  | 7575.000  | 125.0          | LHS       |
| 12    | 7775.000  | 7950.000  | 175.0          | LHS       |
| 13    | 8180.000  | 8775.000  | 595.0          | LHS       |
| 14    | 8300.000  | 8400.000  | 100.0          | RHS       |
| 15    | 9300.000  | 9800.000  | 500.0          | LHS       |
| 16    | 9340.000  | 9475.000  | 135.0          | RHS       |
| 17    | 9950.000  | 10175.000 | 450.0          | BOTH SIDE |
| 18    | 10225.000 | 10300.000 | 75.0           | LHS       |
| 19    | 10750.000 | 10950.000 | 200.0          | LHS       |
| 20    | 11525.000 | 11700.000 | 175.0          | LHS       |
| 21    | 12525.000 | 12900.000 | 750.0          | BOTH SIDE |
| 22    | 13960.000 | 14050.000 | 90.0           | RHS       |
| 23    | 14540.000 | 14600.000 | 120.0          | BOTH SIDE |
| 24    | 15420.000 | 15480.000 | 120.0          | BOTH SIDE |
| 25    | 15670.000 | 15730.000 | 120.0          | BOTH SIDE |
| 26    | 16030.000 | 16220.000 | 380.0          | BOTH SIDE |
| 27    | 16670.000 | 18120.000 | 1450.0         | RHS       |
| 28    | 17840.000 | 17920.000 | 80.0           | LHS       |
| 29    | 18530.000 | 18625.000 | 190.0          | BOTH SIDE |
| 30    | 18900.000 | 19500.000 | 600.0          | LHS       |
| 31    | 19975.000 | 20050.000 | 75.0           | LHS       |
| 32    | 20120.000 | 20200.000 | 160.0          | BOTH SIDE |
| 33    | 20280.000 | 20400.000 | 240.0          | BOTH SIDE |
| 34    | 20530.000 | 20850.000 | 320.0          | LHS       |
| 35    | 21525.000 | 21920.000 | 395.0          | LHS       |
| 36    | 22450.000 | 22560.000 | 220.0          | BOTH SIDE |
| 37    | 22730.000 | 22800.000 | 140.0          | BOTH SIDE |
| 38    | 23480.000 | 23670.000 | 190.0          | LHS       |
| 39    | 24580.000 | 24680.000 | 200.0          | BOTH SIDE |
| 40    | 24870.000 | 25040.000 | 170.0          | LHS       |
| 41    | 25045.000 | 25170.000 | 125.0          | LHS       |
| 42    | 25820.000 | 25995.000 | 175.0          | LHS       |
|       |           |           | <b>10730.0</b> |           |

  
**Executive Engineer**  
 Khonsa Highway Division  
 PWD, Khonsa