

**PROPOSED Service Road 1 GPS Co-ordinates in Forest Area**


**DATUM : WGS-84**

**In Degree.decimals**

**GPS Co-Ordinates of Left Line Boundary of Service Road No.1**

| Point Id | Latitude (N) | Longitude (E) |  | Point Id | Latitude (N) | Longitude (E) |
|----------|--------------|---------------|--|----------|--------------|---------------|
| SR1_L1   | 15.070177°   | 76.512895°    |  | SR1_L31  | 15.070509°   | 76.514599°    |
| SR1_L2   | 15.069976°   | 76.512997°    |  | SR1_L32  | 15.070322°   | 76.514596°    |
| SR1_L3   | 15.070049°   | 76.513182°    |  | SR1_L33  | 15.070181°   | 76.514587°    |
| SR1_L4   | 15.070206°   | 76.513285°    |  | SR1_L34  | 15.070050°   | 76.514578°    |
| SR1_L5   | 15.070358°   | 76.513383°    |  | SR1_L35  | 15.070154°   | 76.514665°    |
| SR1_L6   | 15.070489°   | 76.513468°    |  | SR1_L36  | 15.070282°   | 76.514771°    |
| SR1_L7   | 15.070669°   | 76.513480°    |  | SR1_L37  | 15.070451°   | 76.514843°    |
| SR1_L8   | 15.070827°   | 76.513388°    |  | SR1_L38  | 15.070585°   | 76.514817°    |
| SR1_L9   | 15.070986°   | 76.513297°    |  | SR1_L39  | 15.070719°   | 76.514791°    |
| SR1_L10  | 15.071088°   | 76.513237°    |  | SR1_L40  | 15.070730°   | 76.514827°    |
| SR1_L11  | 15.071225°   | 76.513189°    |  | SR1_L41  | 15.070717°   | 76.514922°    |
| SR1_L12  | 15.071366°   | 76.513174°    |  | SR1_L42  | 15.070667°   | 76.514998°    |
| SR1_L13  | 15.071356°   | 76.513217°    |  | SR1_L43  | 15.070547°   | 76.515053°    |
| SR1_L14  | 15.071087°   | 76.513390°    |  | SR1_L44  | 15.070392°   | 76.515096°    |
| SR1_L15  | 15.070970°   | 76.513513°    |  | SR1_L45  | 15.070195°   | 76.515144°    |
| SR1_L16  | 15.070799°   | 76.513663°    |  | SR1_L46  | 15.070189°   | 76.515166°    |
| SR1_L17  | 15.070654°   | 76.513757°    |  | SR1_L47  | 15.070000°   | 76.515967°    |
| SR1_L18  | 15.070644°   | 76.513848°    |  | SR1_L48  | 15.069889°   | 76.516121°    |
| SR1_L19  | 15.070815°   | 76.513914°    |  | SR1_L49  | 15.069758°   | 76.516303°    |
| SR1_L20  | 15.070932°   | 76.513959°    |  | SR1_L50  | 15.069757°   | 76.516334°    |
| SR1_L21  | 15.070987°   | 76.514030°    |  | SR1_L51  | 15.069848°   | 76.516219°    |
| SR1_L22  | 15.070954°   | 76.514140°    |  | SR1_L52  | 15.069977°   | 76.516054°    |
| SR1_L23  | 15.070775°   | 76.514217°    |  | SR1_L53  | 15.069839°   | 76.516599°    |
| SR1_L24  | 15.070591°   | 76.514225°    |  | SR1_L54  | 15.069707°   | 76.516765°    |
| SR1_L25  | 15.070412°   | 76.514201°    |  | SR1_L55  | 15.069613°   | 76.516863°    |
| SR1_L26  | 15.070273°   | 76.514178°    |  | SR1_L56  | 15.069788°   | 76.516762°    |
| SR1_L27  | 15.070393°   | 76.514292°    |  | SR1_L57  | 15.069626°   | 76.517180°    |
| SR1_L28  | 15.070543°   | 76.514442°    |  | SR1_L58  | 15.069552°   | 76.517249°    |
| SR1_L29  | 15.070634°   | 76.514527°    |  | SR1_L59  | 15.069409°   | 76.517321°    |
| SR1_L30  | 15.070631°   | 76.514582°    |  | SR1_L60  | 15.069336°   | 76.517358°    |

**For Sri Kumaraswamy Mineral Exports Pvt. Ltd.,**

  
**Authorized Signatory**



**PROPOSED Service Road 1 GPS Co-ordinates in Forest Area**

**DATUM : WGS-84**

**In Degree.decimals**

**GPS Co-Ordinates of Right Line Boundary of Service Road No.1**

| Point Id | Latitude (N) | Longitude (E) | Point Id | Latitude (N) | Longitude (E) |
|----------|--------------|---------------|----------|--------------|---------------|
| SR1_R1   | 15.070103°   | 76.512765°    | SR1_R36  | 15.070074°   | 76.514784°    |
| SR1_R2   | 15.069940°   | 76.512869°    | SR1_R37  | 15.070254°   | 76.514893°    |
| SR1_R3   | 15.069777°   | 76.512976°    | SR1_R38  | 15.070427°   | 76.514946°    |
| SR1_R4   | 15.069885°   | 76.513128°    | SR1_R39  | 15.070597°   | 76.514924°    |
| SR1_R5   | 15.069992°   | 76.513279°    | SR1_R40  | 15.070419°   | 76.514982°    |
| SR1_R6   | 15.070151°   | 76.513375°    | SR1_R41  | 15.070220°   | 76.515034°    |
| SR1_R7   | 15.070309°   | 76.513470°    | SR1_R42  | 15.070084°   | 76.515050°    |
| SR1_R8   | 15.070485°   | 76.513575°    | SR1_R43  | 15.070078°   | 76.515161°    |
| SR1_R9   | 15.070665°   | 76.513582°    | SR1_R44  | 15.070163°   | 76.515273°    |
| SR1_R10  | 15.070820°   | 76.513483°    | SR1_R45  | 15.070059°   | 76.515713°    |
| SR1_R11  | 15.070965°   | 76.513391°    | SR1_R46  | 15.069951°   | 76.515861°    |
| SR1_R12  | 15.071086°   | 76.513314°    | SR1_R47  | 15.069842°   | 76.516010°    |
| SR1_R13  | 15.071017°   | 76.513379°    | SR1_R48  | 15.069735°   | 76.516157°    |
| SR1_R14  | 15.070902°   | 76.513467°    | SR1_R49  | 15.069669°   | 76.516246°    |
| SR1_R15  | 15.070764°   | 76.513581°    | SR1_R50  | 15.069609°   | 76.516408°    |
| SR1_R16  | 15.070661°   | 76.513660°    | SR1_R51  | 15.069591°   | 76.516529°    |
| SR1_R17  | 15.070473°   | 76.513756°    | SR1_R52  | 15.069650°   | 76.516607°    |
| SR1_R18  | 15.070437°   | 76.513778°    | SR1_R53  | 15.069775°   | 76.516470°    |
| SR1_R19  | 15.070422°   | 76.513835°    | SR1_R54  | 15.069913°   | 76.516319°    |
| SR1_R20  | 15.070463°   | 76.513858°    | SR1_R55  | 15.069901°   | 76.516367°    |
| SR1_R21  | 15.070634°   | 76.513947°    | SR1_R56  | 15.069780°   | 76.516505°    |
| SR1_R22  | 15.070800°   | 76.514021°    | SR1_R57  | 15.069662°   | 76.516641°    |
| SR1_R23  | 15.070839°   | 76.514085°    | SR1_R58  | 15.069541°   | 76.516778°    |
| SR1_R24  | 15.070611°   | 76.514114°    | SR1_R59  | 15.069470°   | 76.516860°    |
| SR1_R25  | 15.070432°   | 76.514085°    | SR1_R60  | 15.069434°   | 76.516948°    |
| SR1_R26  | 15.070213°   | 76.514049°    | SR1_R61  | 15.069511°   | 76.517046°    |
| SR1_R27  | 15.070165°   | 76.514132°    | SR1_R62  | 15.069629°   | 76.516975°    |
| SR1_R28  | 15.070163°   | 76.514219°    | SR1_R63  | 15.069735°   | 76.516911°    |
| SR1_R29  | 15.070367°   | 76.514411°    | SR1_R64  | 15.069703°   | 76.516997°    |
| SR1_R30  | 15.070347°   | 76.514491°    | SR1_R65  | 15.069575°   | 76.517123°    |
| SR1_R31  | 15.070167°   | 76.514469°    | SR1_R66  | 15.069446°   | 76.517249°    |
| SR1_R32  | 15.070003°   | 76.514449°    | SR1_R67  | 15.069336°   | 76.517358°    |
| SR1_R33  | 15.069923°   | 76.514440°    |          |              |               |
| SR1_R34  | 15.069865°   | 76.514569°    |          |              |               |
| SR1_R35  | 15.069955°   | 76.514712°    |          |              |               |

For Sri Kumaraswamy Mineral Exports Pvt. Ltd.,

  
Authorized Signatory