


**NEW ERUMAIVETTIPALAYAM ROAD**

| Chainage | LEFT SIDE     |                | RIGHT SIDE    |                |
|----------|---------------|----------------|---------------|----------------|
|          | Latitude      | Longitude      | Latitude      | Longitude      |
| 0        | E=406118.7473 | N=1463192.6314 | E=406116.1296 | N=1463187.7943 |
| 100      | E=406206.9852 | N=1463151.6999 | E=406206.5173 | N=1463146.2199 |
| 200      | E=406296.4014 | N=1463165.3198 | E=406299.6522 | N=1463160.8834 |
| 300      | E=406364.6534 | N=1463236.0866 | E=406368.8081 | N=1463232.4827 |
| 400      | E=406399.9663 | N=1463327.1389 | E=406405.1306 | N=1463325.2467 |
| 500      | E=406428.3277 | N=1463420.2077 | E=406433.8291 | N=1463420.1182 |
| 600      | E=406422.2635 | N=1463519.0627 | E=406427.7379 | N=1463519.5925 |
| 700      | E=406406.3086 | N=1463608.3205 | E=406409.5808 | N=1463612.7412 |
| 800      | E=406379.8734 | N=1463695.5027 | E=406384.5881 | N=1463692.6704 |
| 900      | E=406418.122  | N=1463779.8079 | E=406423.6215 | N=1463779.8854 |
| 1000     | E=406428.049  | N=1463879.9164 | E=406433.4039 | N=1463878.6615 |
| 1100     | E=406461.0526 | N=1463974.9224 | E=406466.2358 | N=1463973.0827 |
| 1200     | E=406476.7055 | N=1464072.5807 | E=406482.1415 | N=1464071.744  |
| 1300     | E=406451.9357 | N=1464166.0796 | E=406457.081  | N=1464168.0227 |
| 1400     | E=406444.5638 | N=1464263.8138 | E=406449.7715 | N=1464262.0445 |
| 1500     | E=406465.0504 | N=1464359.0051 | E=406470.5356 | N=1464359.1163 |
| 1523     | E=406464.5955 | N=1464382.3323 | E=406470.1785 | N=1464382.4455 |
| 1573     | E=406463.8271 | N=1464433.1534 |               |                |

  
 Divisional Engineer (H)  
 (C&M) Tiruvallur