



Map showing the Improvements to Hundalli Kakati Road (Improvements with adjusting slope of Hudali, Dharnatti, Mutyanatti Road at Km 16.50 to 17.80 in Belagavi Taluk.)



Prepared
Assistant Executive Engineer,
P.W.&I.W.T. Department,
Sub Division, Belagavi.

GPS Readings (WGS-84)		
Sl No.	Latitude	Longitude
1	15.92523	74.53936
2	15.92540	74.53935
3	15.92549	74.53935
4	15.92672	74.54343
5	15.92659	74.54354
6	15.92533	74.54187
7	15.92535	74.54191


Map showing the Improvements to Hundalli Kakati Road (Improvements with adjusting slope of Hudali, Dharnatti, Mutyanatti Road at Km 16.50 to 17.80 in Belagavi Taluk.)



Assistant Executive Engineer,
P.W.& I.W.T. Department,
Sub Division, Belagavi.

GPS Readings (WGS-84)		
Sl No.	Latitude	Longitude
1	15.92523	74.53936
2	15.92540	74.53935
3	15.92549	74.54183
4	15.92672	74.54343
5	15.92659	74.54354
6	15.92533	74.54187
7	15.92535	74.54191

Map showing the Improvements to Hundalli Kakati Road (Improvements with adjusting slope of Hudali, Dharnatti, Mutyanaatti Road at Km 16.50 to 17.80 in Belagavi Taluk.)



Legend

- CentreLine
- Windinging_Proposed_Road
- Existing_Road
- Kakathi_Village

Shreea

Assistant Executive Engineer,
P.W.&I.W.T. Department,
Sub Division, Belagavi.

GPS Readings (WGS-84)			
Sl No.	Latitude	Longitude	
1	15.92523	74.53936	
2	15.92540	74.53935	
3	15.92549	74.54183	
4	15.92672	74.54343	
5	15.92659	74.54354	
6	15.92533	74.54187	
7	15.92535	74.54191	