

P.R.SURESH ,IFS
DIVISIONAL FOREST OFFICER




Office of the Divisional Forest Officer
Munnar Division, Devikulam
☎: 04865 264237,
Fax:- 04865 264327
E-mail: dfo-mnr.for@ kerala.gov.in

L/M7-3477/2019

Dated: 03.05.2021

Query- Thottiar Power evacuation- 0.7945 Ha

1. The KML file uploaded in the site is a polygon with only ^{four} GPS points which at one area is given below the terrain and also the area as per the KML file comes to 1.22 Ha, which also needs to be explained. So the entire area 0.7945 Ha area whichever is fixed after the joint inspection, shall be given in a polygon mode to the Divisional Forest Officer or Nodal Officer, in soft copy and in hard copy.
2. No proper location Map with survey number, Sketch, Geo reference coordination map of 0.7945 Ha attached. (Two patches are included in the 0.7945 ha ie, 0.2695 Ha in Neriamangalam Village of Ernakulam Distirict and 0.525 Ha in Mamalakandam village of Idukki District hence separate location sketch & survey number is needed).
3. Revised justification , Under taking are needed, and also submitted all documents in CD with proper format (PDF& KML)
4. As per earlier query, A proper Catchment Area Treatment Plan to be given to Divisional Forest Officer/ Nodal Officer.


Divisional Forest Officer
Munnar Division