

/228987/2023

No.Ft.48-314/1997 (FCA)
H.P. Forest Department.

Dated Shimla-1, the

From: Nodal Officer-cum-APCCF (FCA)
O/o Pr.CCF, H.P, Shimla-1.

To: CCF Rampur


Subject:- **Renewal of mining lease of 0.0934 ha(instead of 0.2898 ha) of forest land for already established Stone Crusher at Pashada and approach road to quarry site at Pashada in favour of M/s Bushahar Laghu Udyog VPO Jhakri, Tehsil Rampur Bushahar, Within the jurisdiction of Rampur Forest Division, Distt. Shimla, Himachal Pradesh. (online No. FP/HP/Ind/35171/2018).**

Memo: Kindly refer to your office letter number. 1994 dated 01/08/2023 on the subject cited above.

1. The proposal name is still not corrected as asked by GoI hence, same may be corrected.
2. The NPV calculation sheet as per the revised NPV rate of MoEF & CC letter vide latter dated 06.01.2022 still not been found uploaded online.
3. The detail mentioned / shown in Part-I, Para-E (ii) & (iii) is still not corrected which may be reviewed.
4. The component as mentioned in the layout Plan of the proposed project is not matching with the component mentioned in component wise breakup (Part-I, B-2.4).
5. In reply to point No. 5, it is intimated that EIA is required but copy of the same has not been found uploaded online.
6. In reply to point No.7, DFO Rampur has intimated that the revised field book has been uploaded but no such document has been found uploaded.
7. In reply to point No. 11 the legal status of DA land mentioned in Part-II, Para 2 is still mismatching with Part- II, Sr. No. 5(v) which need to be reviewed and revised.
8. No area has been marked for access/approach road component in revenue paper.
9. The approved and proposed project has not been marked in distinct colour in KML file.
10. In reply point No. 14 the polygon of 0.1964 ha. land in CD form with survival percentage of plantation raised as per the approved Reclamation Plan has not been submitted to this office.

/2023

11. The reply to point No. 15 of GoI is no in consonance with the observation of GoI.
12. The recommendation letter of DFO uploaded in para-II, Para-16 is still found blank.
13. The shape of the diversion area (DA) marked on the SoI map is still not in proper shape as per the revenue record. The revised SoI map of DA may be uploaded against the appropriate column of the portal.



DFO (FCA)
O/o Pr.CCF, H.P, Shimla-1