

Following shortcomings have been noticed in the forest land diversion proposal 9212/2015 which may be attended by the State Govt.

1. Geo reference digital map of the area proposed for diversion and area proposed for CA is not proper. Provide the same afresh showing geo coordinates at various points along the alignment of different linear components. Geo coordinates may be shown in the digital map at minimum 4 points for the area proposed for non linear components if any and the area proposed for CA. The digital map in hard and soft copy may be provided duly authenticated by the DFO.
2. FRA certificate is not available which may be provided on performa along with all enclosures as required by MoEF&CC letter dated 05.07.2013.
3. Muck dumping plan is not available and may be provided.
4. Evacuation plan approved by HP Power Transmission Corp. Ltd is not available which may be provided.
5. Detail of the length and width of the proposed road through forest land and non forest land along with resultant area and bar chart is not available which may be provided.
6. Detail of the transmission line like KV, total length and RoW proposed through forest land and non forest land alongwith detail of no. Of poles to be erected on forest land non forest land may be provided.
7. Dimensions of other components may also be provided, if any.
8. Recommendation of DFO not available and that of CF is not opening. May upload both.