- 1. KML file of area proposed for diversion not uploaded.
- 2. Area proposed for diversion not properly marked on Sol Toposheet attached in part I.
- 3. Components in digital map attached at part I C is not as per detail and area of components given at B 2.4 part I because as per dimension the components are linear in nature but in the map it is not so. In addition area of road and bridge also does not appear to be included in the area proposed for diversion shown on the map.
- 4. Employment generation data not given.
- 5. Muck management plan not provided.
- 6. Site Inspection report of the DFO indicates violation but detailed report on violation as per para 1.9 of chapter 1 of guidelines is not uploaded alongwith action taken report.
- 7. CA scheme not uploaded properly and could not be opened. May upload again.
- 8. Digital map of area proposed for CA giving geo coordinates at minimum 4 points in hard and soft copy duly authenticated by DFO not provided.
- 9. KML file of the area proposed for CA shows that road and khad area is also included in CA which is not proper. May review area selected for CA.
- 10. Chief Secretary Certificate regarding non availability of non forest land for CA not provided on performa prescribed by MoEF&CC Govt. of India.