

कार्यालय प्रमाणीय वनाधिकारी, उत्तरकाशी वन प्रभाण, उत्तरकाशी E.Mail. dfouttarkashifd@gmail.com Fax No-01374222964 Tel.No- 01374222444 प्रांक- 1252 / 12-127, कोटबंगला दिनांक 10 //0/2017

सेवा में,

वन संरक्षक, भागीरथी वृत्त, उत्तराखण्ड मुनिकीरेती।

विषय :- प्रपोजल संख्या-FP/UK/ROAD/20179/2016 जनपद उत्तरकाशी में विकास खण्ड चिन्यालीसौड़ के अन्तर्गत मल्ली-बधाण गांव मोटर मार्ग के थौला से माड़ मोटर मार्ग निर्माण के सम्बन्ध में।

सन्दर्भ :- अधिशासी अभियन्ता, निर्माण खण्ड, लोक निर्माण विभाग, चिन्यालीसौड, उत्तरकाशी की पत्र सं0—1042/3 L.A दिनांक 03.10.2017 तथा इस कार्यालय की पत्र सं0—576/12—1(2) दिनांक 18.08.2017

महोदय.

उपरोक्त विषयक प्रपोजल संख्या FP/UK/ROAD/20179/2016 जनपद उत्तरकाशी में विकास खण्ड चिन्यालीसौड़ के अन्तर्गत मल्ली—बधाण गांव मोटर मार्ग के थौला से माड़ मोटर मार्ग पर लगी आपित्तयों का प्रयोक्ता एजेन्सी द्वारा फार्म—ए संशोधन कर दिया गया है तथा आपित्तयों का निराकरण पूर्व में भी इस कार्यालय के उपरोक्त पत्र के द्वारा प्रेषित किया गया है। पुनः आपित्तयों का निराकरण निम्न प्रकार कर प्रेषित किया जा रहा है।


9 19		**	
क्र.सं.	आपत्तियां	निराकरण	
1	Justification for locating the projectin forest land is not clear uploaded in online Part I D (i). The State Govt may justify the importance and necessity of the proposed road and also gives distance of the villages to be connected by the proposed alignment from existing road network in the area.	Clear Justification, importance and necessity of the proposed road are corrected and uploded in online Part D (i).	
2	The employment details furnished in online Part I. appear to be incorrect.	The employment details corrected in online Part I.	
3	The area mentioned in road component in component wise break up is incorrect in online Part I.	The area corrected in road component in component wise break up in online Part I.	
4	The State Govt may upload the correct map at columm D (ii) (a) of alternative examined in online Part I.	The alternative map corrected and uploded at column D (ii) (a)	
5	The village Level Committee proceeding is undated and the name of gram panchayat written Thaula but signed by representative of New Khalsi. The clarification and correct document may upload at designated place in part-I.	Now date is mentioned in Village Level Committee proceeding. The name of gran panchayat written Thaula but signed by representative of New Khalsi by Mistake. The correct name of gran panchayat is Maad (New Khalsi). The clarification is that it written by mistake and correct document upload in Part-I.	
6	In the Cost Benefit analysis submitted with the reply information in column 1 of both performa VI b and VIC needs to be quantified in monetary terms. Cost over Benefit ratio may also be worked out.	The Cost Benefit analysis information in column 1 of both performa VI b and VI C now quantified in monetary terms and document uploaded.	
7	The details furnished in district profile showing shortfall in stipulated CA against total area diverted in the district. This may be clarified and need necessary correction in online Part II.	Correction in online Part-II.	
8	The State Govt provided CA scheme for equivalent land which is not accepted. The State Govt may provided CA scheme for double the area being diverted and revised the information in online Part-I column L and II column 13 accordingly with revised georefrenced map, KML file, and site suitability certificate.	The CA scheme land bing diverted doublé area.	
9	24 trees per hectare does not account for 0.4 density. The State Govt may review the density and correct the NPV rate accordingly.	The density is 0.4 and the NPV rates aer correct according to the density.	
10	Original copy of the revised document should be furnished to this office.	Original copy of the revised document are attached.	

संलग्न :- उपरोक्तानुसार।


प्रभागीय वनाधिकारी उत्तरकाशी वन प्रभाग उत्तरकाशी।

डिजिटल मैप - जनपद उत्तरकाशी के विकासखण्ड चिन्यालीसौड़ में मल्ली -बधाणगांव मोटर मार्ग से थौला से माड़ मोटर मार्ग के निर्माण हेतु चयनित क्षतिपूरक वृक्षारोपण स्थल 0.5 1 1.5 2Km 78°22'0"E 78°21'0"E 78°190"E 78°20'0"E Dharasu Range Balisi Block Uttarakashi F.D 10 30°34'0'N 98 Chinyall Block Dichli Block 78°21' 33.291" E 78° 21' 10.962" F 30°32' 14926' 30032 12.746 1694 # Paktiri O Dhikiyara 2 30°31' 52.801" N Diagram Tehri Range Tehri F.D. 78°22'0"E 78°20'0"E Legend Proposed Plantation अधिशासी अभियन्ता निमार्ण खण्ड लो0नि0वि0 निमार्ण खण्ड लो0 नि0 वि8 Reserve Forest Boundary विन्यालीसौड उत्तरकाशी चिन्यालीसौड उत्तरकाशी Forest Range Boundary CHECKED TO THE THE Mitarkashi Foresi Division UTTARKASHI

मल्ली - बधाणगांव मोटर मार्ग से थौला से माड़ मोटर मार्ग के निर्माण हेतु चयनित क्षतिपूरक वृक्षारोपण स्थल







Ca Point

निमार्ग खण्ड लो०नि०वि० चिन्यालीसौड उत्तरकाशी

निमार्ण खण्ड लो० नि0 वि0 चिन्यालीसौड़ उत्तरकारी

