101 RCC (GREF) Pin-930101 C/O 56 APO

2030/NOC/Petrol Pump/ 21 /E2

10 Nov 2021

Office of the District Collector Sriganganagar Rajasthan PIN 335 001

NO OBJECTION CERTIFICATE FOR INSTALLATION OF RETAIL OUTLET (PETROL PUMP) ON BRO ROAD BIRDHWAL – PUGAL – BAJJU (KM 43.195 TO KM 43.230) NEAR VILLAGE BHOPALPUR PATHAR NO 23/30, MURBA NO 19 AND KILA NO 16 & 17/2 VILLAGE 2 DOA, TEHSIL SURATGARGH DISTRICT SRIGANGANAGAR

Dear Sir,

- 1. Reference your Office letter No F17(1)() Court /2021/5500 dated 18 Jun 2021.
- 2. On the basis of HQ Dte GBR letter No 2180/PC/DGBR /60/Tp (Plg) dated 29 Aug 2014 and MORT&H letter No RW/NH-33023/01/2017-S&R (R) dated 26 June 2020 Guideline / Norms for grant of permissions for construction of access to Fuel Stations, wayside amenities connecting roads, other properties, rest area complexes and such other facilities on BRO road Birdhwal Pugal Bajju (km 43.195 to km 43.230) at pathar no 23/30, Murba No 19 and kila No 16 & 17/2 village 2 DOA, Tehsil Suratgarh, District Sriganganagar in the State of Rajasthan by M/s Indian Oil Corporation Ltd is issued. The final approval will be given after complection of work as per approved drawings within 6 months.
- 3. This NOC as accorded will be null & void if:-
 - (a) Any breach of the condition / requirement as per MORT&H letter No RW/NH-33023/01/2017-S&R (R) dated 26 June 2020 will happen during construction activity of retail outlet (Petrol pump)
 - (b) The Oil Company / Owner fails to construct the fuel station (Petrol Pump) along with its access as per approved drawing attached at their own cost within 6 months of the issue of Provisional NOC.
 - (c) The final approval will be issued after the construction of the fuel station (Petrol Pump) as per approved drawings and satisfaction of the BRO authorities.
 - (d) The Traffic will not be affected during construction of fuel station (Petrol Pump).
 - (e) Inspections for determining the deviations from prescribed Norms shall be done any time, even after signing of the license deed, by BRO authority. In case of defaults / deviation found during inspections by BRO authority, each deficiency shall be immediately rectified, in no case it should be exceeded 30 days from the date of inspection. The Failure to rectify the identified deficiencies within the prescribed time would lead to de-energizing the fuel station (Petrol Pump) by Indian Oild Corporation Ltd. The re-energizing would be done only on complete rectification and on the authorization by BRO authorities.

- (f) In future for BRO work activities like widening of road, all rectification/restoration work will be done by Oil Company / Owner at their own cost.
- 4. For your information please.

(Vivek Yadav)
Capt
Offg Officer Commanding

Copy to:

(i) Headquarters
49 Border Roads Task Force
Pin: 930 049
C/O 56 APO

(ii) Ekta Middha D/O Bhim Chand Middha Vijainagar, Sribijayanagar Ganganagar - 335704 Phone No 94140 92077 for your info please.

for your info please