


Map Showing DGPS Coordinate of proposed Forest Land for Diversion for Rehabilitation & Upgrading 2 Lane with Pavement Shoulder configuration of Bagrakot to Kafer (Existing km 0+000 to Km 40+000) & Kafer to Reshi Border (Length Km 40+000 to Km 61.250 to Km 76.600 to Km 98+595) of NH-717A in West Bengal State Under Package-IV & Package-V Programme of NH-717A in West Bengal State.



Details of DGPS Coordinate of Proposed forest land for Diversion of Area-116.001 Ha

Package-IV, Segment -I proposed area for Diversion- 38.54 Ha

Segment -I					
Right Side Pillar	UTM Coordinate		Left Side Pillar	UTM Coordinate	
	X	Y		X	Y
R1	656519.4766	2975313.71	L1	656500.383	2975299.12
R2	656453.9009	2975389.206	L2	656434.791	2975374.602
R3	656388.1346	2975464.537	L3	656369.0247	2975449.933
R4	656322.2276	2975539.742	L4	656303.0515	2975525.078
R5	656241.5826	2975597.842	L5	656220.8256	2975580.689
R6	656145.0999	2975621.722	L6	656123.0665	2975598.236
R7	656045.117	2975623.462	L7	656023.0789	2975599.805
R8	655945.1297	2975625.05	L8	655923.2044	2975603.123
R9	655854.787	2975662.575	L9	655835.5202	2975647.821
R10	655779.5328	2975724.447	L10	655757.6294	2975702.551
R11	655679.7319	2975729.653	L11	655657.7076	2975706.506
R12	655580.7789	2975719.751	L12	655559.1999	2975691.103
R13	655516.7688	2975726.443	L13	655480.7265	2975717.72
R14	655606.417	2975769.051	L14	655559.6766	2975768.897
R15	655699.1439	2975797.644	L15	655652.6171	2975797.627
R16	655779.2693	2975852.295	L16	655729.6149	2975858.99
R17	655859.5506	2975878.668	L17	655825.2811	2975869.51
R18	655825.0335	2975940.44	L18	655757.2381	2975879.264
R19	655743.0992	2975955.292	L19	655667.9785	2975858.662
R20	655644.7723	2975951.791	L20	655714.5251	2975918.179
R21	655550.9803	2975977.272	L21	655798.7737	2975943.04
R22	655467.2316	2976028.141	L22	655702.4715	2975935.729
R23	655376.813	2976058.937	L23	655604.3464	2975928.472
R24	655282.9376	2976042.842	L24	655511.4972	2975963.303
R25	655274.4397	2976085.214	L25	655433.1821	2976025.169
R26	655367.8847	2976101.898	L26	655340.31	2976016.162
R27	655464.0892	2976098.878	L27	655248.6105	2976039.347
R28	655563.0547	2976092.046	L28	655242.7577	2976118.693
R29	655643.3334	2976077.508	L29	655337.8052	2976110.337
R30	655661.8178	2976174.05	L30	655430.819	2976131.729
R31	655629.3612	2976268.442	L31	655529.5687	2976122.445
R32	655611.9455	2976364.2	L32	655436.8012	2976149.926
R33	655559.4057	2976311.702	L33	655493.0398	2976189.122
R34	655579.7108	2976214.373	L34	655548.4717	2976189.442
R35	655546.4293	2976143.979	L35	655455.5886	2976221.778
R36	655581.4602	2976197.653	L36	655395.5303	2976300.683
R37	655488.2749	2976227.956	L37	655445.4586	2976345.233
R38	655511.8467	2976222.577	L38	655444.7841	2976441.097

General Manager (Project)

NHIDCL, SIKKIM
1st Floor, 5th Mile, M.P. Golai, Tadong
Gangtok, Sikkim-737102

R39	655557.0324	2976294.325	L39	655434.328	2976539.55
R40	655545.6232	2976393.534	L40	655473.8349	2976630.773
R41	655529.1602	2976492.051	L41	655450.1142	2976718.143
R42	655557.2636	2976583.029	L42	655400.3907	2976802.819
R43	655484.3208	2976561.348	L43	655328.2867	2976868.955
R44	655472.9735	2976464.882	L44	655253.4392	2976933.179
R45	655485.515	2976365.925	L45	655251.3823	2977028.913
R46	655475.9187	2976335.282	L46	655270.0412	2977124.381
R47	655468.7159	2976432.484	L47	655335.7418	2977192.424
R48	655457.3109	2976531.002	L48	655370.9251	2977234.067
R49	655496.4904	2976622.25	L49	655274.6457	2977227.472
R50	655487.0644	2976716.363	L50	655205.6987	2977298.778
R51	655433.2787	2976797.544	L51	655178.7796	2977391.742
R52	655359.9551	2976862.781	L52	655161.965	2977489.484
R53	655288.6597	2976929.802	L53	655124.4027	2977582.022
R54	655273.9257	2977020.446	L54	655115.7271	2977681.407
R55	655292.9556	2977115.844	L55	655107.9466	2977780.088
R56	655363.9508	2977175.056	L56	655167.8263	2977857.556
R57	655411.761	2977247.574	L57	655205.6759	2977941.805
R58	655319.6187	2977243.031	L58	655139.059	2978013.691
R59	655240.2366	2977294.622	L59	655141.9406	2978110.285
R60	655202.8915	2977383.113	L60	655086.6899	2978182.113
R61	655188.5955	2977481.209	L61	655005.0729	2978234.087
R62	655151.7797	2977573.926	L62	655005.4086	2978331.27
R63	655140.7724	2977672.837	L63	654982.5341	2978420.337
R64	655130.575	2977771.597	L64	654885.6856	2978417.889
R65	655192.66	2977847.118	L65	654803.9403	2978465.472
R66	655232.1879	2977933.502	L66	654758.4058	2978554.065
R67	655172.4412	2978008.764	L67	654714.7326	2978642.741
R68	655164.8648	2978101.734	L68	654724.0792	2978741.653
R69	655129.4538	2978189.44	L69	654705.2276	2978839.807
R70	655038.5892	2978229.261	L70	654713.0186	2978936.933
R71	655028.0816	2978322.767	L71	654706.4303	2979034.854
R72	655019.1972	2978418.379	L72	654739.311	2979126.826
R73	654930.8314	2978452.108	L73	654824.2952	2979178.653
R74	654836.9651	2978460.281	L74	654912.805	2979225.169
R75	654790.8291	2978548.349	L75	655008.7118	2979253.067
R76	654740.5666	2978634.289	L76	655075.9666	2979259.988
R77	654748.6736	2978733.044	L77	654976.0665	2979255.702
R78	654730.691	2978831.298	L78	654898.6498	2979310.044
R79	654740.8734	2978929.004	L79	654916.4975	2979402.985
R80	654729.654	2979026.263	L80	654948.6219	2979495.377
R81	654763.6777	2979116.901	L81	654874.6473	2979551.795
R82	654850.8695	2979165.61	L82	654819.1948	2979629.549
R83	654940.3028	2979210.081	L83	654794.6814	2979726.498
R84	655037.5995	2979229.597	L84	654816.0934	2979818.86
R85	655108.7571	2979256.762	L85	654909.4609	2979840.648



General Manager (Projects)
NHIDCL, SIKKIM
1st Floor, 5th Mile, M.P. Gotal, Tadong,
Gangtok, Sikkim-737102


R86	655022.3673	2979281.554	L86	654928.3194	2979874.401
R87	654929.8383	2979303.639	L87	654860.4065	2979942.569
R88	654939.7706	2979394.026	L88	654890.4648	2980032.25
R89	654973.6788	2979486.801	L89	654852.9812	2980067.163
R90	654919.3464	2979564.223	L90	654773.03	2980089.465
R91	654846.0388	2979621.288	L91	654765.7027	2980164.887
R92	654821.5254	2979718.237	L92	654704.5408	2980225.92
R93	654840.9491	2979808.35	L93	654630.2444	2980257.794
R94	654938.3524	2979813.532	L94	654536.0692	2980235.301
R95	654969.8565	2979878.848	L95	654473.0875	2980306.058
R96	654888.9203	2979934.866	L96	654449.2394	2980403.116
R97	654916.1964	2980020.545	L97	654382.1166	2980470.638
R98	654898.6913	2980092.879	L98	654460.5342	2980511.892
R99	654800.9228	2980082.11	L99	654530.4915	2980582.473
R100	654808.7717	2980174.731	L100	654569.4671	2980524.917
R101	654744.6203	2980238.367	L101	654553.9208	2980431.728
R102	654663.3836	2980254.991	L102	654595.497	2980489.012
R103	654581.6538	2980260.184	L103	654657.0765	2980564.621
R104	654500.0962	2980297.829	L104	654660.5923	2980657.567
R105	654476.8201	2980395.067	L105	654651.3442	2980563.26
R106	654411.1979	2980463.974	L106	654585.2319	2980580.481
R107	654486.1465	2980500.35	L107	654581.438	2980674.272
R108	654556.4439	2980554.854	L108	654559.6002	2980767.6
R109	654522.0003	2980463.937	L109	654504.302	2980727.762
R110	654574.6316	2980395.77	L110	654492.4358	2980635.031
R111	654618.741	2980480.067	L111	654448.7121	2980566.762
R112	654679.8986	2980556.065	L112	654373.8991	2980631.341
R113	654693.8473	2980654.862	L113	654276.9273	2980628.787
R114	654628.1142	2980646.339	L114	654192.6982	2980661.178
R115	654609.2751	2980571.914	L115	654103.2451	2980621.732
R116	654613.9121	2980668.663	L116	654149.6937	2980564.962
R117	654582.798	2980758.988	L117	654210.5586	2980488.819
R118	654523.4972	2980799.02	L118	654281.812	2980421.963
R119	654468.0137	2980715.859	L119	654327.0843	2980335.384
R120	654472.4227	2980619.703	L120	654281.3117	2980266.711
R121	654411.5402	2980630.336	L121	654257.9169	2980354.755
R122	654321.9726	2980661.613	L122	654183.1232	2980419.136
R123	654231.5674	2980678.81	L123	654098.2221	2980469.264
R124	654146.8228	2980658.96	L124	654023.5006	2980534.113
R125	654064.3701	2980617.276	L125	653955.5701	2980603.665
R126	654130.7872	2980550.176	L126	653982.98	2980694.192
R127	654190.4069	2980472.308	L127	654064.556	2980750.046
R128	654262.8255	2980407.122	L128	654129.9323	2980769.747
R129	654302.3722	2980319.475	L129	654035.7632	2980739.176
R130	654285.3851	2980346.684	L130	653951.9238	2980709.256
R131	654222.3741	2980419.993	L131	653993.6747	2980778.677
R132	654137.6382	2980470.71	L132	654089.471	2980804.733

General Manager (Projects)

NHIDCL, SIKKIM

1st Floor, 5th Mile, M.P. Golai, Tadong
Gangtok, Sikkim - 737102

Map Showing DGPS Coordinate of proposed Forest Land for Diversion for Rehabilitation & Upgrading 2 Lane with Pavement Shoulder configuration of Bagrakot to Kafer (Existing km 0+000 to Km 40+000) & Kafer to Reshi Border (Length Km 40+000 to Km 61.250 to Km 76.600 to Km 98+595) of NH-717A in West Bengal State Under Package-IV & Package-V Programme of NH-717A in West Bengal State.



R133	654063.8218	2980536.468	L133	654180.6742	2980843.443
R134	653984.6525	2980596.188	L134	654278.4656	2980847.325
R135	654007.7827	2980683.748	L135	654298.1842	2980935.073
R136	654093.4419	2980727.631	L136	654247.7373	2981017.652
R137	654164.2972	2980768.727	L137	654295.6247	2981099.237
R138	654175.1518	2980818.295	L138	654343.827	2981177.295
R139	654274.086	2980818.706	L139	654346.4076	2981276.86
R140	654331.8405	2980893.674	L140	654338.07	2981221.198
R141	654288.4734	2980978.6	L141	654319.0787	2981125.507
R142	654292.5725	2981068.333	L142	654244.9172	2981163.025
R143	654363.8144	2981134.545	L143	654188.6984	2981105.177
R144	654365.4491	2981233.827	L144	654121.2452	2981116.876
R145	654339.5864	2981316.119	L145	654139.6252	2981211.975
R146	654311.5318	2981239.761	L146	654147.7235	2981309.861
R147	654301.9046	2981142.54			
R148	654226.2571	2981189.914			
R149	654165.7361	2981123.824			
R150	654166.2075	2981169.317			
R151	654169.1995	2981267.174			

Package-IV, Segment -II proposed area for Diversion- 0.878 Ha

Segment -II					
Right Side Pillar	UTM Coordinate		Left Side Pillar	UTM Coordinate	
	X	Y		X	Y
R1	654246.5321	2981564.48	R1	654200.2791	2981590.988
R2	654257.9939	2981641.12	R2	654250.834	2981669.261
R3	654310.8674	2981725.426	R3	654300.6077	2981755.737
R4	654391.7602	2981775.604	R4	654387.2969	2981800.497

Package-IV, Segment -III proposed area for Diversion- 26.784 Ha

Segment -III					
Right Side Pillar	UTM Coordinate		Left Side Pillar	UTM Coordinate	
	X	Y		X	Y
R1	655536.9775	2984546.352	L1	655514.6784	2984534.75
R2	655497.2161	2984631.243	L2	655471.9317	2984620.029
R3	655479.5524	2984729.336	L3	655457.4128	2984718.233
R4	655493.6813	2984826.681	L4	655462.3489	2984817.334
R5	655520.5819	2984922.034	L5	655495.7256	2984910.783
R6	655568.3817	2985000.699	L6	655525.4675	2985002.509
R7	655614.6186	2985083.591	L7	655590.1924	2985072.328
R8	655585.8643	2985178.324	L8	655563.55	2985167.184
R9	655591.45	2985277.323	L9	655568.804	2985266.131
R10	655573.9111	2985375.562	L10	655550.1568	2985364.283

General Manager (Projects)

NHIDCL, SIKKIM

1st Floor, 5th Mile, M.P. Golai, Tadong
Gangtok, Sikkim-737102

R11	655569.4196	2985474.925	L11	655547.1484	2985463.795
R12	655517.8621	2985559.522	L12	655496.3517	2985548.58
R13	655433.8662	2985609.111	L13	655408.6383	2985592.532
R14	655337.7979	2985633.375	L14	655314.4366	2985620.483
R15	655253.9677	2985682.726	L15	655227.7498	2985656.107
R16	655234.4502	2985692.947	L16	655187.9336	2985713.044
R17	655329.5553	2985665.177	L17	655284.09	2985705.913
R18	655426.9397	2985650.631	L18	655380.4872	2985689.52
R19	655513.1467	2985602.786	L19	655470.609	2985649.754
R20	655597.4999	2985645.573	L20	655561.1224	2985639.695
R21	655624.8461	2985740.766	L21	655600.9362	2985729.478
R22	655647.9671	2985830.433	L22	655610.0699	2985825.918
R23	655735.7229	2985874.388	L23	655694.6529	2985873.702
R24	655804.472	2985939.842	L24	655759.0091	2985947.438
R25	655900.7187	2985952.601	L25	655721.6958	2985923.597
R26	655857.3877	2986003.414	L26	655643.4377	2985908.768
R27	655762.2321	2985980.457	L27	655705.0364	2985971.326
R28	655795.7661	2986023.429	L28	655774.1469	2986041.422
R29	655851.5372	2986079.958	L29	655805.5611	2986065.289
R30	655761.4649	2986073.16	L30	655713.026	2986027.378
R31	655671.9917	2986029.662	L31	655638.4071	2985964.179
R32	655636.673	2986019.447	L32	655617.27	2986033.613
R33	655714.978	2986080.262	L33	655694.2674	2986096.138
R34	655804.3021	2986124.602	L34	655782.605	2986142.768
R35	655903.6397	2986131.437	L35	655881.0752	2986155.589
R36	655996.6066	2986161.658	L36	655976.3634	2986176.795
R37	656041.5251	2986248.617	L37	656022.0556	2986262.823
R38	656074.626	2986342.491	L38	656053.9417	2986357.192
R39	656139.7543	2986412.765	L39	656114.8307	2986427.387
R40	656075.2712	2986436.848	L40	656047.9496	2986363.909
R41	656016.3413	2986356.735	L41	655995.5115	2986278.966
R42	655958.7648	2986275.723	L42	655925.182	2986208.498
R43	655884.737	2986210.088	L43	655832.4587	2986179.576
R44	655786.492	2986211.66	L44	655734.7436	2986193.876
R45	655688.4833	2986208.912	L45	655636.7717	2986173.838
R46	655592.7532	2986182.416	L46	655548.2724	2986129.894
R47	655502.7994	2986141.73	L47	655452.2067	2986102.121
R48	655408.1696	2986110.232	L48	655384.6575	2986035.822
R49	655348.1167	2986032.576	L49	655307.275	2985974.273
R50	655275.2864	2985967.324	L50	655235.3594	2985963.633
R51	655313.238	2986021.983	L51	655293.8342	2986036.147
R52	655330.0184	2986115.283	L52	655299.7063	2986129.269
R53	655309.1879	2986211.615	L53	655271.0957	2986214.466
R54	655242.3366	2986206.794	L54	655280.4988	2986117.974
R55	655257.4438	2986108.576	L55	655263.0817	2986024.134
R56	655228.1314	2986051.518	L56	655208.3943	2986065.867
R57	655236.2949	2986149.588	L57	655212.0703	2986164.723


General Manager (Project)

NHIDCL, SIKKIM
1st Floor, 5th Mile, M.P. Golai, Tadong
Gangtok, Sikkim-737102

R58	655216.8388	2986246.762	L58	655185.9959	2986260.554
R59	655153.5429	2986318.72	L59	655108.4063	2986320.248
R60	655083.3917	2986387.276	L60	655056.0334	2986402.012
R61	655109.5068	2986480.138	L61	655089.9046	2986494.419
R62	655157.4073	2986564.677	L62	655118.5717	2986567.095
R63	655089.8897	2986559.101	L63	655068.4754	2986485.006
R64	655029.4507	2986484.382	L64	655000.6128	2986412.42
R65	654958.5674	2986416.359	L65	654937.8282	2986342.312
R66	654914.1125	2986332.872	L66	654949.688	2986250.996
R67	654912.2193	2986282.141	L67	654876.3099	2986293.354
R68	654883.8583	2986373.068	L68	654863.9216	2986387.509
R69	654952.3352	2986443.308	L69	654932.7267	2986457.596
R70	654939.578	2986527.755	L70	654887.5354	2986512.281
R71	654849.8442	2986565.496	L71	654800.6581	2986560.185
R72	654757.5222	2986603.895	L72	654709.457	2986600.722
R73	654686.7918	2986669.772	L73	654647.4594	2986678.405
R74	654615.3005	2986738.982	L74	654571.3548	2986742.624
R75	654547.7304	2986811.515	L75	654505.9826	2986817.559
R76	654463.2515	2986861.499	L76	654419.0713	2986864.876
R77	654399.0926	2986935.789	L77	654369.8767	2986950.119
R78	654385.5807	2987034.241	L78	654363.8676	2987049.185
R79	654406.4272	2987131.184	L79	654386.6178	2987145.577
R80	654418.351	2987213.753	L80	654373.4921	2987215.347
R81	654447.0145	2987267.671	L81	654426.1419	2987283.873
R82	654545.4416	2987262.491	L82	654523.1834	2987290.234
R83	654559.2526	2987329.869	L83	654510.7835	2987325.125
R84	654486.6922	2987393.491	L84	654449.4554	2987403.812
R85	654459.1843	2987484.054	L85	654436.2205	2987499.155
R86	654434.6319	2987579.557	L86	654403.5164	2987593.27
R87	654384.2426	2987664.018	L87	654349.7643	2987675.941
R88	654388.8029	2987755.135	L88	654369.4098	2987769.322
R89	654477.136	2987799.401	L89	654456.544	2987815.119
R90	654547.3801	2987869.962	L90	654527.9461	2987884.182
R91	654586.0408	2987960.004	L91	654564.9998	2987974.826
R92	654632.2129	2988047.379	L92	654612.7239	2988061.649
R93	654703.2811	2988117.527	L93	654683.8912	2988131.711
R94	654753.154	2988203.757	L94	654731.9555	2988218.611
R95	654773.1911	2988298.679	L95	654753.6895	2988312.96
R96	654807.1182	2988388.157	L96	654784.8908	2988403.188
R97	654835.5996	2988483.83	L97	654815.1123	2988498.495
R98	654860.1789	2988580.531	L98	654837.4386	2988595.632
R99	654855.3454	2988679.999	L99	654828.1285	2988694.842
R100	654856.3149	2988777.527	L100	654836.0285	2988792.124
R101	654865.3625	2988876.163	L101	654845.0583	2988890.763
R102	654915.6799	2988960.22	L102	654895.8756	2988974.819
R103	654968.1963	2989043.533	L103	654948.7931	2989057.728
R104	655014.6994	2989130.43	L104	654994.8288	2989145.109

General Manager (Projects)
NHIDCL, SIKKIM
1st Floor, 5th Mile, M.P. Golai, Tadong
Gangtok, Sikkim-737102

Map Showing DGPS Coordinate of proposed Forest Land for Rehabilitation & Upgrading 2 Lane with Pave Shoulder



R105	655076.083	2989205.774	L105	655056.4792	2989220.08
R106	655136.9699	2989284.745	L106	655117.5039	2989298.994
R107	655205.8671	2989357.219	L107	655186.3361	2989371.528
R108	655264.2581	2989436.513	L108	655242.1787	2989451.526
R109	655279.2772	2989532.655	L109	655259.8662	2989546.856
R110	655364.0885	2989584.667	L110	655344.1107	2989599.479
R111	655448.7395	2989636.14	L111	655428.5791	2989651.197
R112	655546.183	2989646.996	L112	655524.0953	2989666.857

Package-V, Segment -IV proposed area for Diversion- 37.392 Ha

Segment -IV					
Right Side Pillar	UTM Coordinate		Left Side Pillar	UTM Coordinate	
	X	Y		X	Y
R1	655698.8107	2989722.268	L1	655688.647	2989755.744
R2	655747.4203	2989808.662	L2	655744.3734	2989836.512
R3	655811.6715	2989882.723	L3	655806.6249	2989912.678
R4	655889.9086	2989942.138	L4	655879.9583	2989975.481
R5	655954.6317	2990016.218	L5	655951.1787	2990044.577
R6	656033.5981	2990077.453	L6	656030.0136	2990105.942
R7	656092.4891	2990156.803	L7	656089.7549	2990184.206
R8	656182.7385	2990195.097	L8	656181.4537	2990219.637
R9	656276.7947	2990213.331	L9	656276.1113	2990239.345
R10	656346.3965	2990142.318	L10	656350.1452	2990174.324
R11	656419.806	2990075.58	L11	656423.9929	2990107.963
R12	656490.9679	2990080.952	L12	656440.2564	2990103.635
R13	656420.7648	2990146.125	L13	656379.1273	2990177.709
R14	656398.1605	2990240.73	L14	656349.7727	2990268.31
R15	656336.5553	2990317.634	L15	656301.7908	2990352.459
R16	656289.2369	2990401.903	L16	656217.9935	2990395.558
R17	656245.1048	2990433.427	L17	656243.9723	2990457.858
R18	656333.4225	2990394.346	L18	656336.8444	2990425.99
R19	656372.3573	2990304.477	L19	656376.8554	2990337.026
R20	656460.8238	2990266.322	L20	656458.8617	2990292.222
R21	656462.3172	2990348.958	L21	656403.885	2990368.273
R22	656398.91	2990423.916	L22	656348.5664	2990450.639
R23	656333.1071	2990497.335	L23	656266.0189	2990504.115
R24	656240.5067	2990530.274	L24	656174.0201	2990518.147
R25	656236.1576	2990547.428	L25	656234.8068	2990572.179
R26	656309.9243	2990611.946	L26	656298.7039	2990645.765
R27	656310.7135	2990706.527	L27	656254.9075	2990728.751
R28	656266.1219	2990779.126	L28	656264.4011	2990804.804
R29	656328.3751	2990851.045	L29	656301.4639	2990887.106
R30	656337.4618	2990947.544	L30	656325.8958	2990981.639
R31	656361.5805	2991043.87	L31	656341.4011	2991080.184
R32	656378.3366	2991141.735	L32	656372.5693	2991172.297



General Manager (Projects)
NHIDCL, SIKKIM
1st Floor, 5th Mile, M.P. Golai, Tadong
Gangtok, Sikkim-737102

R33	656431.4119	2991223.213	L33	656407.3842	2991259.717
R34	656428.7735	2991323.136	L34	656406.9493	2991359.51
R35	656456.8913	2991417.153	L35	656448.3338	2991449.75
R36	656513.8907	2991497.479	L36	656511.9508	2991523.597
R37	656608.1563	2991523.727	L37	656606.9136	2991548.07
R38	656675.7717	2991589.881	L38	656659.8251	2991625.451
R39	656702.6354	2991686.149	L39	656689.9142	2991720.723
R40	656744.1765	2991776.939	L40	656734.9768	2991809.904
R41	656784.0706	2991867.77	L41	656773.8099	2991901.15
R42	656849.4892	2991940.505	L42	656838.4952	2991974.36
R43	656895.047	2992029.376	L43	656890.2892	2992059.054
R44	656975.2548	2992085.958	L44	656965.0922	2992119.313
R45	657023.3876	2992172.62	L45	657018.9953	2992202.001
R46	657069.9616	2992256.976	L46	657035.4693	2992291.621
R47	657043.5085	2992352.788	L47	657018.5543	2992389.242
R48	657061.889	2992448.686	L48	657050.6706	2992482.503
R49	657075.4214	2992545.402	L49	657065.2803	2992578.724
R50	657141.0643	2992619.237	L50	657136.9648	2992648.314
R51	657203.063	2992696.953	L51	657194.5736	2992729.51
R52	657259.359	2992779.382	L52	657253.4604	2992810.13
R53	657310.3323	2992863.484	L53	657292.559	2992899.311
R54	657347.4838	2992954.557	L54	657323.7428	2992990.906
R55	657317.744	2993045.102	L55	657258.8097	2993063.327
R56	657269.6711	2993123.884	L56	657254.6143	2993159.153
R57	657263.2536	2993219.637	L57	657227.0287	2993211.328
R58	657231.2403	2993313.761	L58	657136.5718	2993190.717
R59	657203.0042	2993408.45	L59	657053.9022	2993199.599
R60	657151.3502	2993366.997	L60	657126.2209	2993242.736
R61	657202.4883	2993281.981	L61	657128.2785	2993261.638
R62	657171.2897	2993213.258	L62	657031.7449	2993248.083
R63	657078.3242	2993202.628	L63	656937.6912	2993279.429
R64	657164.68	2993230.354	L64	656849.2527	2993321.29
R65	657159.4149	2993300.691	L65	656902.877	2993362.041
R66	657066.0806	2993267.778	L66	656995.7397	2993343.253
R67	656970.8398	2993293.55	L67	657091.0675	2993362.388
R68	656878.7714	2993329.542	L68	657049.4846	2993441.771
R69	656936.8013	2993316.02	L69	657021.5646	2993533.01
R70	657033.0495	2993334.332	L70	657020.7135	2993630.988
R71	657121.5721	2993361.182	L71	657068.3364	2993712.979
R72	657076.6379	2993446.408	L72	657132.6437	2993784.82
R73	657046.7868	2993535.703	L73	657209.4806	2993846.251
R74	657044.6368	2993633.838	L74	657298.0228	2993888.185
R75	657103.9019	2993707.287	L75	657387.8063	2993931.403
R76	657161.8016	2993785.726	L76	657474.5338	2993979.135
R77	657243.9393	2993842.048	L77	657567.2771	2994007.323
R78	657336.1237	2993876.994	L78	657524.4389	2994042.905
R79	657425.7401	2993921.088	L79	657433.8124	2994001.696

General Manager (Projects)

NHIDCL, SIKKIM

1st Floor, 5th Mile, M.P. Golai, Tadong
Gangtok, Sikkim-737102

R80	657509.452	2993974.237	L80	657340.4327	2993966.814
R81	657601.1647	2994001.536	L81	657242.5112	2993964.283
R82	657558.7897	2994072.459	L82	657164.4284	2993905.598
R83	657464.3663	2994043.27	L83	657140.8012	2993968.263
R84	657371.3091	2994007.726	L84	657225.9512	2994020.333
R85	657277.0402	2993985.774	L85	657309.8058	2994074.586
R86	657186.2065	2993958.697	L86	657380.8993	2994144.803
R87	657177.7487	2993960.177	L87	657471.3467	2994182.608
R88	657260.9559	2994015.493	L88	657553.1089	2994238.906
R89	657342.1764	2994072.908	L89	657643.0193	2994278.887
R90	657418.1984	2994135.512	L90	657732.646	2994316.693
R91	657504.7743	2994179.659	L91	657820.5785	2994352.867
R92	657590.9008	2994228.442	L92	657874.8127	2994433.023
R93	657676.9406	2994275.488	L93	657954.8173	2994492.566
R94	657772.9805	2994296.91	L94	658035.8574	2994549.808
R95	657847.7175	2994354.901	L95	658071.6475	2994641.48
R96	657910.2429	2994427.554	L96	658133.9715	2994716.085
R97	657991.5321	2994484.908	L97	658207.7712	2994779.904
R98	658063.9499	2994551.365	L98	658285.8435	2994842.392
R99	658105.6346	2994637.828	L99	658332.0271	2994928.542
R100	658161.966	2994717.697	L100	658361.4054	2995022.428
R101	658241.7863	2994776.389	L101	658415.2301	2995104.825
R102	658318.458	2994840.388	L102	658505.9992	2995143.22
R103	658362.2603	2994928.723	L103	658473.9403	2995143.428
R104	658387.3295	2995024.936	L104	658383.1868	2995106.007
R105	658450.3494	2995099.761	L105	658351.4565	2995165.695
R106	658544.1019	2995130.834	L106	658445.6182	2995197.196
R107	658503.8336	2995186.38	L107	658515.7923	2995262.791
R108	658410.7904	2995152.67	L108	658466.8771	2995235.619
R109	658390.7399	2995150.377	L109	658445.5613	2995298.811
R110	658483.0201	2995188.181	L110	658534.9644	2995336.396
R111	658546.675	2995262.421	L111	658490.1775	2995364.813
R112	658629.667	2995308.231	L112	658545.5545	2995432.109
R113	658566.6229	2995332.428	L113	658627.3057	2995489.538
R114	658599.0075	2995363.095	L114	658569.0933	2995493.889
R115	658678.9987	2995396.072	L115	658617.1035	2995548.774
R116	658601.0571	2995415.778	L116	658709.2412	2995582.825
R117	658515.5179	2995372.531	L117	658801.8407	2995620.527
R118	658584.1955	2995427.817	L118	658900.5213	2995635.459
R119	658665.0909	2995486.443	L119	658979.0118	2995685.773
R120	658759.2095	2995507.276	L120	659063.5776	2995731.747
R121	658706.7626	2995553.631	L121	659159.0129	2995711.297
R122	658719.1792	2995560.965	L122	659244.2879	2995668.985
R123	658811.8372	2995598.502	L123	659304.1301	2995590.199
R124	658910.7135	2995612.417	L124	659274.6418	2995643.621
R125	658992.6356	2995660.717	L125	659220.535	2995727.596
R126	659073.6805	2995709.295	L126	659147.3265	2995794.409




General Manager (Projects)

NHIDCL, SIKKIM

1st Floor, 5th Mile, M.P. Gofai, Tadong
Gangtok, Sikkim-737102

Map Showing DGPS Coordinate of proposed Forest Land for Diversion for Rehabilitation & Upgrading 2 Lane with Pave Shoulder configuration of Bagrakot to Kafer (Existing km 0+000 to Km 40+000) & Kafer to Reshi Border (Length Km 40+000 to Km 61.250 to Km 76.600 to Km 98+595) of NH-717A in West Bengal State Under Package-IV & Package-V Programme of NH-717A in West Bengal State.



R127	659169.2359	2995686.714	L127	659206.2898	2995826.447
R128	659239.1897	2995625.348	L128	659263.4667	2995746.415
R129	659312.1919	2995560.146	L129	659346.7523	2995691.408
R130	659324.7132	2995629.056	L130	659432.8553	2995651.522
R131	659263.751	2995706.533	L131	659530.9052	2995663.508
R132	659321.8288	2995678.645	L132	659627.046	2995688.466
R133	659405.2654	2995626.681	L133	659712.3159	2995639.934
R134	659504.1192	2995632.448	L134	659800.7882	2995593.85
R135	659599.6719	2995661.177	L135	659861.0696	2995517.172
R136	659687.9392	2995627.96	L136	659919.8502	2995437.571
R137	659775.6203	2995580.679	L137	659999.6518	2995377.726
R138	659838.921	2995507.471	L138	660096.9989	2995389.173
R139	659896.6831	2995427.021	L139	660175.4352	2995335.641
R140	659974.231	2995364.033	L140	660257.7876	2995283.667
R141	660069.8096	2995360.496	L141	660307.9	2995205
R142	660153.3232	2995325.927	L142	660345.9	2995188
R143	660233.3713	2995271.634	L143	660388.8	2995159
R144	660279.9	2995199	L144	660423.9	2995128
R145	660342.2	2995163	L145	660471.2	2995106
R146	660376.7	2995136	L146	660508.7	2995075
R147	660418.1	2995107	L147	660567.1	2995065
R148	660464.3	2995082	L148	660604.4	2995037
R149	660498.1	2995053	L149	660633	2994996
R150	660553	2995043	L150	660668	2994968
R151	660586.9	2995021			
R152	660618	2994978			
R153	660656.2	2994947			

Package-V, Segment -V proposed area for Diversion- 11.928 Ha

Segment -V					
Right Side Pillar	UTM Coordinate		Left Side Pillar	UTM Coordinate	
	X	Y		X	Y
R1	660847.8	2995306	L1	660823.4	2995299
R2	660839.2	2995401	L2	660814.7	2995394
R3	660881.9	2995482	L3	660862.1	2995495
R4	660913.6	2995577	L4	660883.9	2995578
R5	660965.5	2995662	L5	660942.2	2995669
R6	660989.8	2995771	L6	660960	2995764
R7	661040	2995837	L7	661016	2995841
R8	661105.9	2995900	L8	661089.6	2995918
R9	661201.1	2995918	L9	661193.8	2995939
R10	661271.4	2995991	L10	661252.8	2996006
R11	661359	2996038	L11	661344.7	2996057

General Manager (Projects)

NHIDCL, SIKKIM

1st Floor, 5th Mile, M.P. Gelai, Tadong
Gangtok, Sikkim-737102

R12	661429.5	2996097	L12	661414.7	2996116
R13	661510.1	2996146	L13	661496.5	2996166
R14	661603.5	2996161	L14	661606.5	2996185
R15	661715.5	2996168	L15	661695.4	2996182
R16	661790	2996216	L16	661776.5	2996236
R17	661879.9	2996257	L17	661866.7	2996277
R18	661963.9	2996298	L18	661955.3	2996320
R19	662058	2996338	L19	662042.2	2996361
R20	662146.1	2996372	L20	662131.1	2996391
R21	662237.7	2996414	L21	662220.5	2996433
R22	662331	2996465	L22	662312.5	2996482
R23	662423.4	2996450	L23	662412.6	2996479
R24	662517.9	2996474	L24	662506.3	2996496
R25	662605.4	2996516	L25	662593.8	2996537
R26	662701.4	2996533	L26	662689.9	2996554
R27	662770.3	2996601	L27	662758.7	2996623
R28	662863.6	2996632	L28	662852.2	2996653
R29	662886.6	2996714	L29	662829.8	2996678
R30	662797.4	2996686	L30	662741.7	2996631
R31	662710.5	2996638	L31	662659.6	2996618
R32	662728.1	2996662	L32	662716.7	2996683
R33	662816.2	2996708	L33	662804.1	2996730
R34	662890.1	2996772	L34	662878.5	2996794
R35	662966.3	2996837	L35	662954.7	2996859
R36	663027.9	2996915	L36	663015.8	2996937
R37	663113.3	2996965	L37	663101.3	2996987
R38	663178.7	2997040	L38	663167.3	2997061
R39	663245.1	2997114	L39	663232.6	2997136
R40	663324.3	2997172	L40	663312.9	2997193
R41	663413.9	2997217	L41	663402.5	2997238
R42	663510.3	2997241	L42	663499	2997262
R43	663577.6	2997313	L43	663566.1	2997335
R44	663670.8	2997330	L44	663659.7	2997359
R45	663769.8	2997336	L45	663758.1	2997358
R46	663860.5	2997375	L46	663849.1	2997396
R47	663887.9	2997292	L47	663909.1	2997341
R48	663948.7	2997218	L48	663939.1	2997250
R49	664030	2997163			
R50	664109.4	2997195			
R51	664028.8	2997215			

Package-V, Segment -6 proposed area for Diversion- 0.48 Ha

Segment -VIII					
Right Side Pillar	UTM Coordinate		Left Side Pillar	UTM Coordinate	
	X	Y		X	Y


General Manager (Projects)
 NHIDCL, SIKKIM
 1st Floor, 5th Mile, M.P. Golai, Tadong
 Gangtok, Sikkim-737102

R1	658120.5	3002457	L1	658097.9	3002459
R2	658125.7	3002509	L2	658101	3002498
R3	658145.7	3002547	L3	658123.6	3001988
R4	658178.1	3002579	L4	658160.6	3002596
R5	658215.5	3002604	L5	658207.1	3002626


 General Manager (Projects)
 NHIDCL, SIKKIM
 1st Floor, 5th Mile, M.E. C. Road, Gangtok
 Gangtok: 735 101