



PLATE-VII

SKETCH-1



SKETCH-2

METHOD OF RECLAMATION AND AFFORESTATION IN MINED OUT AREA



5/11/1
Forest Range Officer
Sukinda Range
Asst. Conservator of Forests
Cuttack Forest Division.

[Signature]
(GANESH PRASAD SAHU)
Head (Ferro Alloys Production)
Ferro Alloys & Minerals Division

[Signature]
Divisional Forest Officer
Cuttack Forest Division