प्रारुप-2.4

Performa for comparison between identified alignments

Performa for comparison between identified alignments						
s.no.	Item	Alignment 1	Alignment 2			
1	Detail of Route, vis a vis Topography of the area main feature and Description of the Alignment	Alignment take off Km6.0 of Budakedar – Jala Motor Road. Grade of this Alignment are 1:24 fall & Level, It shall run through Naap, Civil Soyam &Land,Reserve forrest. Zero H.P. Band provided in this Alignment.In this alignment reservr forrest required only 0.315 hectares	Alignment take off Km 6.0 of Budakedar – Jala Motor Road Motor Road. Grade of this Alignment are 1:22,1:20,1:20 Rise ,& Level, It shall run through Naap, Civil Soyam & Forest Land.Zero H.P. Band provided in this Alignment In this alignment reservr forrest required only 0.35			
2	Length of Road	1.50 K.M.	hectares 2.0 K.M.			
3	Bridging/Culvert requirement No. and Length	01( 6 mtr Span)	01( 6 mtr Span)			
4	Geometric					
	(a) Gradients	1:24 fall, & Level	1:24,1:22 Rise,1:20 Rise,& Level			
	(b) Curves, H.P Bends	0	0			
5	Existing Means of communication, mule path, jeep, Tracks etc.	Mule & path	Mule & path			
6	Right of way, bringing out. construction on account of built up areas, monuments and other structure  1. Naap Land 2. Van Panchayat Land 3. Civil Soyam Land 4. Reserve Forest Land					
7	(a) Terrain & Soil Condition.	As Per Geologist Report	As Per Geologist Report			
	(i) Cliffs and gorges. (ii) Drainage characteristics of the area including supceptibility to flooding. (iii) General elevation of the road indicating maximum and					

	minimum height negotiated by main ascends and discends. (iv) Variations extants and types.		
8	Climate Condition: (a) Temperature max. & min. reading.	Max. 35 C & Min. 3 C	Max. 35 C & Min. 3 C
	(b) Rainfall data average annual peak intensities monthly distribution (to the extent available).	1200 mm	1200 mm
	(c) Snowfall data average annual peak intensities monthly distribution (to the	Negligible	Negligible
	extent available) . (d) Wind direction and velocities.	From North to South with moderate Velocity	From North to South with moderate Velocity
	(e) Fog Condition. (f) Exposure to sun. (g) Unusual weather condition like cloud brust etc.	Partialy Well expose toSun Negligible	Partialy Well expose toSun Negligible
			,
9	Facilities resources.  (a) Landing ground.  (b) Dropping Zone.  (c) Food stuffs.  (d) Labour local availability and need for import.	Yes Nill Budakedar 50% Labors available Lacally & rest From Nepal	Yes Nill Budakedar 50% Labors available Lacally 8 rest From Nepal
	(e) Construction material (Timber, Bamboo, Sand, Stone, Shingle etc. extent of their availability and lead involved.	Stone & timber available with in 20 Kms	Stone & timber available with in 20 Kms
10	Value of land, agricultural land, Irrigated land, bult up land, forest land etc,	As per District Circle Rates	As per District Circle Rates
11	Approximate Const. Cost.	1.00 crore	1.0 crore
12	Access point indicating possibility of induction of equipment	Budakedar	Budakedar
13	Period required for construction	1year	1 year
14	Strategic Consideration		
15	Important villages, towns and	All Nearest Village Including Budakedar Market	All Nearest Village Including Budakedar Market

	markets centers to be connected		
16	Recreational potential.	Will Increse	Will Increse
17	Economic Factors:  (a) Population served by the alignment.	Approximate	Approximate
	(b) Agricultures and economic potential of the area.	Good	Good
18	other major development projects being taken up electric projects etc.	Negligible	Negligible
19	(i) Misc. Such as camping sites (ii) Law and other problem (iii) Royalty (iv) Availability of contractors for collection and carriage of construction material (v) working period available for construction of work.	Nill Nill Nill	Nill Nill Nill Nill
20	Total No. of trees to be removed .	60	110
21	Average Density of forest cover	0.4%	0.4%
22	Total No. of Merits	Alignment accepted by Villagers & Elected Public reprentatives of the Area     Zero H.P. Band     Alignment is Passing through stable area	Zero H.P. Band     Alignment is Passing through steep area
23	Total No. of Demerits		Alignment is not accepted by Villagrer     Elected Public reprentatives of the Area     Zero H.P. Band

RECOMMENDATIONS:

Alignment no. (1) Recommended for approval long more economical, useful & technically

feasible.

Junior Engineer/ P.WD Assistant Engineer | Gent

Texecutive Engineer)

Note - Signature and approval of the concerned DFO is essential.

अविज्ञानिक विज्ञानिक

अभियन्ता

## प्रारूप-2.4

परियोजना का नाम :-जिला योजना के अन्तर्गत जनपद टिहरी गढवाल के विकास खण्ड भिलंगना में झाला - कोटी मोटर मार्ग का नव निर्माण का कार्य लम्बाई (0.40 +1.10 km)

## वैकल्पिक समेरखण को निरस्त करने का किये जाने का प्रमाण पत्र

सर्वेक्षण के उपरान्त इस कार्य के निर्माण हेतु 02 समरेखणों पर विचार किया गया है प्रस्ताव में संलग्न रंगीन गुगल मानचित्र में अलग-अलग रंग से दर्षाया गया है।

समरेखण नं0:— 1 के अनुसार यह नव निर्मित मोटर मार्ग जनपद टिहरी गढवाल के विकास खण्ड भिलंगना में बूढ़ाकेदार —झाला मोटर मार्ग के कि0मी0—06 के अन्तिम बिन्दू पर निर्मित लौह सेतू के पाष्विसे षुरू होकर 1.50 कि0मी0 लम्बाई पूर्ण करता है इस समरेखण में कोई हेयर पिन बैण्ड प्रस्तावित नहीं किया गया है।तथा मार्ग में कम आरक्षित भूमि की आवष्यकता है। साथ ही तकनीकी दृष्टि एवं मानकों के अनुसार मोटर मार्ग का ग्रेड भी रखा गया है जिससे मोटर मार्ग के निर्माण से अधिकाधिक आबादी भी लाभान्वित होगी इसके अनुसार मोटर मार्ग की लम्बाई भी कम आती है साथ ही इस समरेरखण से समस्त ग्रामवासी एवं जनप्रतिनिधि में सहमत है।

समरेखण नं0:— 2 के अनुसार यह नव निर्मित मोटर मार्ग भी जनपद टिहरी गढवाल के विकास खण्ड भिलंगना में बूढाकंदार —झाला मोटर मार्ग के कि0मी0—06 के अन्तिम बिन्दू पर निर्मित लौह सेतू के पांच से प्रस्तावित पुरू होकर 2.0 कि0मी0 लम्बाई पूर्ण करता है इस समरेखण में कोई हेयर पिन बैण्ड प्रस्तावित नहीं किया गया है।समरेखण की लम्बाई अधिक होने के कारण तथा समरेखण का अधिकतर भाग वन क्षेत्र, सिविल, नाप भूमि से होकर गुजर रहा हैं साथ ही मार्ग का कुछ भाग कच्ची भूमि से होकर भी गुजरता है। इस समरेखण में मोटर होकर गुजर रहा हैं साथ ही मार्ग का कुछ भाग कच्ची भूमि से होकर भी गुजरता है। इस समरेखण में मोटर मार्ग के निर्माण के फलस्वरूप वृक्ष, कृषि योग्या भूमि अधिक प्रभावित होगी। तकनीकी दृष्टि एवं मानको के अनुसार मोटर मार्ग का ग्रेड भी सही नहीं मिलता है। एवं अधिक से अधिक आबादी भी लाभन्वित नहीं हो रही है इस समरेखण से समस्त ग्रामवासी एवं जनप्रतिनिधि में सहमत नहीं है।

उक्त को ध्यान में रखते हुये समरेखण नं0−2 को निरस्त कर समरेखण नं0−1 को अनुमोदित किया गया है इन दोनो संमेरखणों का भू—वैज्ञानिक द्वारा भी निरीक्षण किया गया है। एवं उनके द्वारा समरेखण नं0−1 को मार्ग निर्माण हेतु तकनीकी, पर्यावरणीय एवं भू—गर्भीया दृष्टि से उपर्युक्त पाया गया है। ;भू—वैज्ञानिक रिपोर्ट की आख्या की छाया प्रति संलग्न अतः लोक निर्माण विभाग के मानकों के अनुसार आने वाले आरक्षित वन भूमि 0.315 है0, सिविल सोयम भूमि 0.469 है0, वन भूमि को हस्तान्तरित करने हेतु वन संरक्षण अधिनियम 1980 के अन्तर्गत यह प्रस्ताव गठित कर प्रेषित किया जा रहा है।

प्रस्तावित परियोजना हेतु 02 समेरखणों पर विचार किया गया किन्तु समरेखण नं0—2 को ग्राम सभा की आपित्ति एवं समरेखण की लम्बाई अधिक होने के कारण निरस्त किया गया है। प्रस्तावित समरेखण —1 को ग्राम सभा की सहमित तथा कम वृक्षों की संख्या के कारण उचित पाया गया। तकनीकी पर्यावरणीय एवं भू—गर्भीय दृष्टि से भी समरेखण 2 की अपेक्षा समरेखण 1 को उपयुक्त पाया गया है।

कनिष्ठं अभियन्ता, अ०ख०,लो०नि०वि०,घनसाली अस्थाई खण्ड अभिन्ता, पियान सहायक अभिन्ता, अ०ख०, लो०नि०वि०, घनसासी अधियासी ले ० न ० विभाग अञ्जीविषासी अम्बर्गानी अ०ख०, ली०नि०वि०, घनसाली