

PIPE LINE CROSSING THROUGH FOREST

ORAIYUR ALIGNMENT

| Chainage | Easting | Northing | Degree,Minute Second | | Degree,Decimal | |
|----------|------------|-------------|----------------------|-------------------|----------------|-------------|
| | | | Latitude | Longitute | Latitude | Longitute |
| 0 | 336539.621 | 1308360.008 | 11°49' 53.3913"N | 79°29' 58.222 "E | 11.83149759 | 79.49950612 |
| 30 | 336536.554 | 1308330.169 | 11°49' 52.4197"N | 79°29' 58.12 6"E | 11.83122769 | 79.49947944 |
| 60 | 336533.833 | 1308300.296 | 11°49' 51.447"N | 79°29' 58.041 4"E | 11.83095749 | 79.49945594 |
| 90 | 336530.939 | 1308270.436 | 11°49' 50.4747"N | 79°29' 57.95 11"E | 11.83068740 | 79.49943085 |
| 120 | 336527.856 | 1308240.595 | 11°49' 49.5029"N | 79°29' 57.8 545"E | 11.83041748 | 79.49940403 |
| 150 | 336524.760 | 1308210.755 | 11°49' 48.5312"N | 79°29' 57.7 575"E | 11.83014757 | 79.49937709 |
| 180 | 336521.587 | 1308180.924 | 11°49' 47.5598"N | 79°29' 57.6 58"E | 11.82987773 | 79.49934944 |
| 210 | 336518.374 | 1308151.098 | 11°49' 46.5886"N | 79°29' 57.5 571"E | 11.82960793 | 79.49932142 |
| 240 | 336515.192 | 1308121.272 | 11°49' 45.6173"N | 79°29' 57.4 573"E | 11.82933814 | 79.49929369 |
| 270 | 336512.044 | 1308091.438 | 11°49' 44.6458"N | 79°29' 57.3 586"E | 11.82906828 | 79.49926627 |
| 300 | 336508.710 | 1308061.625 | 11°49' 43.6749"N | 79°29' 57.2 537"E | 11.82879860 | 79.49923714 |
| 330 | 336504.852 | 1308031.881 | 11°49' 42.7062"N | 79°29' 57.1 315"E | 11.82852951 | 79.49920320 |
| 351.391 | 336502.964 | 1308010.570 | 11°49' 42.0123"N | 79°29' 57.0729"E | 11.82833676 | 79.49918693 |