प्रारुप-13

Performa for comparison between identified alignments

1		Performa for comparison between identified alignments					
	s.no.	700111	Alignment 1	Alignment 2			
	1	Detail of Route, vis a vis Topography of the area main feature and Description of the Alignment	Alignment take off Km-14 Of Gadoliya- Ghansali Motor Road and connect to Km- 97.00 of Uttarakashi- Lambgaon -Ghansali- Tilwara (SH-15) Motor Road. Grade of this Alignment are 1:24 Fall,1:20 Rise, 1:24 Rise & Level, It shall run through Naap, Civil Soyam & Forest Land. 02 H.P. Band provided in this Alignment	Alignment take off Km-15 Of Gadoliya- Ghansali Motor Road and connect to Km- 97.00 of Uttarakashi- Lambgaon -Ghansali- Tilwara (SH-15) Motor Road. Grade of this Alignment are 1:24 Fall'1:20 Rise & 1:24 Rise, It shall run through Naap, Civil Soyam & Forest Land. 03 H.P. Band provided in this Alignment			
	2	Length of Road	2.250 K.M.	1.550 K.M.			
	3	Bridging requirement No. and Length	1 No 96 meter	1 No 110 meter			
	4	Geometric					
		(a) Gradients	1:24 Fall'1:20 Rise,1:24 Rise, & Level	1:24 Rise,1:20 Rise,& 1:24 Fall			
		(b) Curves, H.P Bends	2	3			
	5	Existing Means of communication, mule path, jeep, Tracks etc.	Mule& path	Mule& path			
	6	Right of way, bringing out. construction on account of built up areas, monuments and other structure  1. Naap Land 2. Van Panchayat Land 3. Civil Soyam Land 4. Reserve Forest Land	550 - 350 1450	- - - 1550			
	7	(a) Terrain &Soil Condition.	As Per Geologist Report	As Per Geologist Report			
		(vi) Cliffs and gorges. (vii) Drainage characteristics of the area including supceptibility to flooding. (viii) General elevation of the road indicating maximum and minimum height negotiated by main ascends and discends. (ix) Variations extants and types.					

8	Climate Condition:  (a) Temperature max. & min. reading.	Max. 40 C & Min.15 C	Max. 40 C & Min. 15 C
9	(b) Rainfall data average annual peak intensities monthly distribution (to the extent available).	1000 mm	1000 mm
	(c) Snowfall data average annual peak intensities monthly distribution (to the	Negligible	Negligible
	extent available) . (d) Wind direction and velocities.	From North to South with moderate Velocity	From North to South with moderate Velocity
	<ul><li>(e) Fog Condition.</li><li>(f) Exposure to sun.</li><li>(g) Unusual weather condition like cloud brust etc.</li></ul>	Partialy Well expose toSun Negligible	Partialy Well expose toSun Negligible
9	Facilities resources.  (a) Landing ground.  (b) Dropping Zone.	Yes Nill	Yes Nill
	<ul><li>(c) Food stuffs.</li><li>(d) Labour local availability and need for import.</li></ul>	Ghansali 50% Labors available Lacally & rest From Nepal	Ghansali 50% Labors available Lacally & rest From Nepal
	(e) Construction material (Timber, Bamboo, Sand, Stone, Shingle etc. extent of their availability and lead involved.	Stone & timber available with in 30-40 Kms	Stone & timber available with in 30-40 Kms
10	Value of land, agricultural land, Irrigated land, bult up land, forest land etc,	As per District Circle Rates	As per District Circle Rates
11	Approximate Const. Cost.	4.50 crore	4.60 crore
12	Access point indicating possibility of induction of equipment	Ghansali	Ghansali
13	Period required for construction	5 year	5 year
14	Strategic Consideration		
15	Important villages, towns and markets centers to be connected	All Nearest Village Including Ghansali Market	All Nearest Village Including Ghansali Market
16	Recreational potential.	Will Increse	Will Increse
17	Economic Factors: (a) Population served by the alignment.	Approximate	Approximate

18	other major development projects being taken up electric projects etc.	Negligible	Negligible
19	(i) Misc. Such as camping sites (ii) Law and other problem (iii) Royalty (iv) Availability of contractors for collection and carriage of construction material (v) working period available for construction of work.	Nill Nill Nill	Nill Nill Nill
20	Total No. of trees to be removed .	130	108
21	Average Density of forest cover .	0.4%	0.4%
22	Total No. of Merits	Alignment accepted by Villagers & Elected Public reprentatives of the Area     H.P. Band     Alignment is Passing through stable area	<ol> <li>Alignment is Passing through steep area</li> </ol>
23	Total No. of Demerits	Alignment is not accepted by Villarers & Elected Public reprentatives of the Area	

## RECOMMENDATIONS:

Alignment no. (2) Recommended for approval being more economical, useful & technically feasible.

Junior Engineer/ P.WD

Assistant Engineer P.W.D

Executive Engineer

P.W.D

भिलंगना रेंज, धनसाली े टिइए वन प्रसाय