


Location Map showing Diversion of 4.05 Ha. Forest Land in Compartment Nos. 594 (Part) & 596 (Part) of Mutchukota RF in Mutchukota (N) Beat of Gooty Range in Ananthapuramu Division for Grant of Renewal of Mining/Quarry Lease in favour of M/s. Sri Sai Minerals, Proprietor : Sri Peram Nagi Reddy.



ABSTRACT

Mining Lease Area : 3.38 Ha.
Safety Zone Area : 0.67 Ha.
Total Renewal Lease Area: 4.05 Ha.



Scale 1:50000
Map Datum : Wgs 84

FIELD BOOK

Sl. No.	Point ID	Northing	Easting	Elevation	Latitude	Longitude
01	M1	1643228.842	804766.179	287.742	14.84604472	77.83181182
02	M2	1643280.443	804796.611	287.255	14.84650720	77.83210041
03	M3	1643244.671	804866.971	269.661	14.84617611	77.83274939
04	M4	1643188.275	804889.731	261.105	14.84566424	77.83295406
05	M5	1643136.333	804910.786	258.722	14.84519278	77.83314341
06	M6	1643097.035	804926.754	261.619	14.84483608	77.83328703
07	M7	1643033.692	804931.014	272.122	14.84426359	77.83331911
08	M8	1642956.671	804936.187	281.430	14.84356748	77.83335808
09	M9	1642946.298	804939.407	285.289	14.84347344	77.83338674
10	M10	1642939.681	804862.172	289.522	14.84342253	77.83266895
11	M11	1643010.687	804855.684	273.619	14.84406447	77.83261708
12	M12	1643058.473	804826.214	263.832	14.84449936	77.83234911
13	M13	1643109.966	804791.419	264.676	14.84496835	77.83203214
14	M14	1643146.895	804767.513	278.403	14.84530456	77.83181456
15	M15	1643197.363	804766.303	283.977	14.84576044	77.83180927
16	S1	1643230.813	804758.659	289.852	14.84606337	77.83174223
17	S2	1643290.383	804793.879	288.609	14.84659727	77.83207621
18	S3	1643250.399	804872.804	268.877	14.84622717	77.83280423
19	S4	1643191.979	804896.464	260.515	14.84569692	77.83301700
20	S5	1643139.905	804917.436	258.692	14.84522428	77.83320556
21	S6	1643098.762	804934.122	262.490	14.84485083	77.83335563
22	S7	1643034.122	804938.457	270.891	14.84426662	77.83338826
23	S8	1642957.085	804943.665	281.473	14.84357036	77.83342754
24	S9	1642939.300	804949.706	285.238	14.84340907	77.83348153
25	S10	1642929.583	804855.604	293.945	14.84333209	77.83260679
26	S11	1643007.354	804848.774	275.356	14.84403517	77.83255253
27	S12	1643054.764	804819.589	264.334	14.84446663	77.83228717
28	S13	1643105.892	804785.104	265.025	14.84493228	77.83197304
29	S14	1643144.384	804760.057	278.147	14.84528274	77.83174505
30	S15	1643197.316	804758.844	285.608	14.84576086	77.83174001

For SRI SAI MINERALS

Proprietor

FOREST BEAT OFFICER
MUTCHUKOTA NORTH

FOREST SECTION OFFICER
MUTCHUKOTA

Forest Range Officer
Gooty.

District Forest Officer
ANANTHAPURAMU.

0 5 10 Kilometers

INDEX

- RF Boundary Line
- Sri Sai Minerals Mining Lease Area
- Sri Sai Minerals Safety Zone Area
- Existing Cartracks