

Alternative Examined for the Project.

SRNO


Route No complete Remane

1) Route No 1 208, 209, 210, 213, 218, 219 Not recommended due to full river dam & hilly area.

2) Route No 2 208, 207, 200, 203, 205, 212, 218, 219 Not recommended due to hilly & steep slope area

3) Route No 3 208, 207, 200, 186, 205, 204, 184, 215, 214, 216, 218, 219 Recommended due to line passing along the road & less hilly area

Shows this



Dy. Executive Engineer
M.S. Elect. Dist. Co. Ltd.
Sub. Divn. 1 CHOPDA