


MAP OF 33KV T/L FROM JANG SUB-STATION TO THINGBU SUB STATION UNDER TAWANG SOCIAL FORESTRY DIVISION



SL.No.	POLE No.	LATITUDE	LONGITUDE
1	Gantry JANG Sub-Station	27 34 28.2	91 59 0.55
2	P-1	27 34 27.57	91 58 59.39
3	P-2	27 34 26.05	91 59 0.21
4	P-3	27 34 24.67	91 59 2.12
5	P-4	27 34 23.12	91 59 4.14
6	P-5	27 34 22.11	91 59 7.32
7	P-6	27 34 23.54	91 59 8.62
8	P-7	27 34 24.05	91 59 10.51
9	P-8	27 34 24.77	91 59 12.36
10	P-9	27 34 25.53	91 59 14.03
11	P-10	27 34 25.64	91 59 15.49
12	P-11	27 34 27.02	91 59 17.85
13	P-12	27 34 27.55	91 59 18.83
14	P-13	27 34 28.31	91 59 20.86
15	P-14	27 34 28.66	91 59 23.71
16	P-15	27 34 29.65	91 59 25.63
17	P-16	27 34 32.19	91 59 27.03
18	P-17	27 34 33.54	91 59 28.8
19	P-18	27 34 35.18	91 59 30.43
20	P-19	27 34 35.75	91 59 33.16
21	P-20	27 34 35.76	91 59 35.09
22	P-21	27 34 37.26	91 59 35.41
23	P-22	27 34 37.94	91 59 35.66
24	P-23	27 34 39.32	91 59 37.5
25	P-24	27 34 41.42	91 59 39.82
26	P-25	27 34 44.4	91 59 38.73
27	P-26	27 34 46.83	91 59 37.22
28	P-27	27 34 50.32	91 59 35.65
29	P-28	27 34 51.32	91 59 34.7
30	P-29	27 34 52.62	91 59 33.77
31	P-30	27 34 54.28	91 59 34.49
32	P-31	27 34 55.71	91 59 34.58
33	P-32	27 34 56.99	91 59 33.18
34	P-33	27 34 58.04	91 59 32.55
35	P-34	27 35 1.75	91 59 33.14
36	P-35	27 35 3.74	91 59 30.86
37	P-36	27 35 3.73	91 59 28.6
38	P-37	27 35 3.06	91 59 26.56
39	P-38	27 35 2.82	91 59 24.56
40	P-39	27 35 3.68	91 59 22.66
41	P-40	27 35 4.68	91 59 21.3
42	P-41	27 35 5.36	91 59 20.2
43	P-42	27 35 7.23	91 59 19.09
44	P-43	27 35 9.05	91 59 18.3
45	P-44	27 35 10.56	91 59 16.72
46	P-45	27 35 12.01	91 59 14.66
47	P-46	27 35 13.69	91 59 13.26
48	P-47	27 35 15.35	91 59 13.21
49	P-48	27 35 17.53	91 59 13.52
50	P-49	27 35 19.5	91 59 12.95
51	P-50	27 35 20.14	91 59 11.34
52	P-51	27 35 21.01	91 59 10.42
53	P-52	27 35 20.14	91 59 10.41
54	P-53	27 35 25.14	91 59 10.79
55	P-54	27 35 25.83	91 59 11.69
56	P-55	27 35 26.75	91 59 13.07
57	P-56	27 35 28.32	91 59 14.08
58	P-57	27 35 31.15	91 59 14.78
59	P-58	27 35 33.22	91 59 13.23
60	P-59	27 35 34.33	91 59 13.88
61	P-60	27 35 34.54	91 59 15.44
62	P-61	27 35 36	91 59 16.09
63	P-62	27 35 38.02	91 59 16.18
64	P-63	27 35 40.32	91 59 15.43
65	P-64	27 35 41.94	91 59 15.01
66	P-65	27 35 45.2	91 59 16
67	P-66	27 35 46.99	91 59 16.79
68	P-67	27 35 48.72	91 59 17.06
69	P-68	27 35 51.29	91 59 17.73
70	P-69	27 35 54.31	91 59 17.96
71	P-70	27 35 56.79	91 59 18.3
72	P-71	27 35 59	91 59 18.43
73	P-72	27 36 1.42	91 59 20.81
74	P-73	27 36 2.6	91 59 21.82
75	P-74	27 36 4.13	91 59 23.27
76	P-75	27 36 5.57	91 59 24.09
77	P-76	27 36 7.92	91 59 25.17
78	P-77	27 36 9.39	91 59 27.23
79	P-78	27 36 11.19	91 59 27.95
80	P-79	27 36 13.53	91 59 28.51
81	P-80	27 36 14.87	91 59 28.82
82	P-81	27 36 16.72	91 59 29.39
83	P-82	27 36 18.71	91 59 29.59
84	P-83	27 36 20.46	91 59 29.58
85	P-84	27 36 22.21	91 59 29.38
86	P-85	27 36 23.52	91 59 29.62
87	P-86	27 36 25.08	91 59 29.72
88	P-87	91 59 29.72	91 59 30.66
89	P-88	27 36 26.88	91 59 32.22
90	P-89	27 36 28.51	91 59 33
91	P-90	27 36 30.44	91 59 33.97
92	P-91	27 36 32.1	91 59 35.49
93	P-92	27 36 33.32	91 59 36.57
94	P-93	27 36 33.85	91 59 38.76
95	P-94	27 36 34.35	91 59 40.21
96	P-95	27 36 35.01	91 59 42.32
97	P-96	27 36 35.87	91 59 44.46
98	P-97	27 36 36.7	91 59 46.76
99	P-98	27 36 37.11	91 59 48.39
100	P-99	27 36 37.54	91 59 50.4

101	P-100	27 36 38.65	91 59 51.37
102	P-101	27 36 39.99	91 59 52.53
103	P-102	27 36 40.95	91 59 53.98
104	P-103	27 36 41.61	91 59 55.61
105	P-104	27 36 43.18	91 59 56.69
106	P-105	27 36 44.33	91 59 58.76
107	P-106	27 36 46.62	92 0 1.29
108	P-107	27 36 46.62	92 0 2.85
109	P-108	27 36 48.98	92 0 4.34
110	P-109	27 36 50.68	92 0 5.27
111	P-110	27 36 51.57	92 0 7.41
112	P-111	27 36 51.19	92 0 8.51
113	P-112	27 36 52.57	92 0 10.11
114	P-113	27 36 54.14	92 0 11.95
115	P-114	27 36 56.14	92 0 14.12
116	P-115	27 36 56.86	92 0 15.43
117	P-116	27 36 57.59	92 0 17.32
118	P-117	27 36 57.93	92 0 18.96
119	P-118	27 36 57.75	92 0 20.71
120	P-119	27 36 58.31	92 0 22.82
121	P-120	27 36 59.34	92 0 24.75
122	P-121	27 37 0.35	92 0 26.49
123	P-122	27 37 0.72	92 0 28.24
124	P-123	27 37 1.42	92 0 29.87
125	P-124	27 37 3.09	92 0 32.01
126	P-125	27 37 3.66	92 0 34.38
127	P-126	27 37 4.94	92 0 36.3
128	P-127	27 37 6.41	92 0 37.09
129	P-128	27 37 7.33	92 0 39.05
130	P-129	27 37 7.9	92 0 41.2
131	P-130	27 37 9.35	92 0 43.15
132	P-131	27 37 11.2	92 0 43.76
133	P-132	27 37 12.48	92 0 44.69
134	P-133	27 37 13.95	92 0 46.5
135	P-134	27 37 15.81	92 0 47.58
136	P-135	27 37 17.6	92 0 48.19
137	P-136	27 37 19.37	92 0 49.41
138	P-137	27 37 20.48	92 0 50.5
139	P-138	27 37 21.72	92 0 51.58
140	P-139	27 37 22.52	92 0 53.8
141	P-140	27 37 23.18	92 0 55.62
142	P-141	27 37 24.94	92 0 56.11
143	P-142	27 37 25.69	92 0 57.13
144	P-143	27 37 26.39	92 0 58.69
145	P-144	27 37 27.21	92 1 0.72
146	P-145	27 37 27.75	92 1 2.65
147	P-146	27 37 28.28	92 1 4.77
148	P-147	27 37 28.37	92 1 7.25
149	P-148	27 37 29.65	92 1 9.42
150	P-149	27 37 30.9	92 1 11.42
151	P-150	27 37 32.69	92 1 12.86
152	P-151	27 37 33.52	92 1 14.75
153	P-152	27 37 34.56	92 1 15.81
154	P-153	27 37 34.84	92 1 17.41
155	P-154	27 37 35.41	92 1 19.59
156	P-155	27 37 36.96	92 1 20.51
157	P-156	27 37 38	92 1 22.7
158	P-157	27 37 38.88	92 1 23.94
159	P-158	27 37 40.04	92 1 26.22
160	P-159	27 37 41.13	92 1 29.1
161	P-160	27 37 41.82	92 1 32.1
162	P-161	27 37 40.9	92 1 34.24
163	P-162	27 37 41.54	92 1 36.39
164	P-163	27 37 41.94	92 1 38.65
165	P-164	27 37 42.84	92 1 41.1
166	P-165	27 37 42.85	92 1 43.06
167	P-166	27 37 42.7	92 1 44.88
168	P-167	27 37 42.26	92 1 47.4
169	P-168	27 37 42.08	92 1 49.35
170	P-169	27 37 41.58	92 1 52.01
171	P-170	27 37 41.79	92 1 53.65
172	P-171	27 37 41.87	92 1 55.62
173	P-172	27 37 42.6	92 1 57.98
174	P-173	27 37 42.84	92 2 0.31
175	P-174	27 37 42.99	92 2 2.68
176	P-175	27 37 43.32	92 2 4.18
177	P-176	27 37 43.37	92 2 5.6
178	P-177	27 37 43.9	92 2 7.38
179	P-178	27 37 45.44	92 2 9.63
180	P-179	27 37 45.04	92 2 13.17
181	P-180	27 37 45.09	92 2 14.74
182	P-181	27 37 44.29	92 2 17.01
183	P-182	27 37 44.53	92 2 19.7
184	P-183	27 37 44.71	92 2 21.24
185	P-184	27 37 44.2	92 2 22.71
186	P-185	27 37 43.92	92 2 24.53
187	P-186	27 37 42.99	92 2 26.51
188	P-187	27 37 42.59	92 2 28.99
189	P-188	27 37 42.67	92 2 31.29
190	P-189	27 37 43.49	92 2 33.4
191	P-190	27 37 43.42	92 2 37.16
192	P-191	27 37 43.63	92 2 38.98
193	P-192	27 37 43.61	92 2 40.19
194	P-193	27 37 44.01	92 2 41.68
195	P-194	27 37 44.21	92 2 43.43
196	P-195	27 37 44.09	92 2 44.93
197	P-196	27 37 44.4	92 2 46.93
198	P-197	27 37 45.05	92 2 49.66
199	P-198	27 37 46.09	92 2 51.81
200	P-199	27 37 46.82	92 2 53.81