


Sl no	Chainage	Longitude	Latitude	Easting	Northing
1	23210	E86° 32' 13.4"	N25° 05' 45.1"	453320.3937	2775642.427
2	23230	E86° 32' 12.9"	N25° 05' 44.2"	453,306.29	2775614.792
3	23250	E86° 32' 12.3"	N25° 05' 43.4"	453289.4042	2775590.242
4	23280	E86° 32' 11.7"	N25° 05' 42.5"	453272.5036	2775562.617
5	23300	E86° 32' 11.3"	N25° 05' 41.8"	453,261.23	2775541.124
6	23330	E86° 32' 10.7"	N25° 05' 40.9"	453244.3252	2775513.498
7	23350	E86° 32' 10.0"	N25° 05' 39.8"	453224.6024	2775479.731
8	23370	E86° 32' 09.6"	N25° 05' 39.0"	453213.314	2775455.162


 Executive Engineer
 N. H. Division
 Lakhisarai at Munger
