



एन एम डी सी लिमिटेड NMDC Limited

(भारत सरकार का उद्यम / A Government of India Enterprise)
दोणिमलै लौह अयस्क खान / Donimalai Iron Ore Mine

ISO 9001 : 2008
ISO 14001 : 2004
OHSAS 18001 : 2007
SA 8000 : 2008

दोणिमलै उपनगर - 583 118
जिल्ला - बल्लारी, कर्नाटक
Donimalai Township - 583 118
Dist-Ballari, Karnataka

Justification for locating the project in forest Area:

The proposed Screening Plant & Tailing dams are planned to ensure best possible interconnection with minimal disturbance to the existing facilities and surrounding forest. This is planned to make best use of contours between existing lump ore Con.501 and Fine ore Conv.411 from EL 722 m to EL 690m with less disturbance to existing vegetation. Considering the topography, storage silos are envisaged instead of open stockpile in order to have more live volume, clean & safe storage and easy retrieval of material, which are eco-friendly.

The Kumaraswamy Iron Ore mine is located at hill top where the iron ore deposits occur and the ancillary facilities like Screening Plant -II, Tailing dam-I, Tailing dam-II & Pipe line are need to be built to support the mining process in non mineralized area near ancillary facilities. All the ancillary facilities for the proposed projects are located in Donimalai. These facilities will be used for processing of ore from KIOM. To reduce the energy consumption for the transport of tailings from the screening plant to the tailing dam. A slope will be maintained between the SP-II and Tailing dam-I and tailing dam-II.

Thus the location of tailing dam is selected near and below the height of screening plant. The same is available at the site. Water availability for screening is also in existence, so no extra infrastructure will be required. To avoid the environmental implication of the screening and tailings on villagers, it is away from the residential area also. Already Environment Management Plan, Bio-Diversity Conservation Plan are in implementation in the region. Hence construction of SP-II along with tailing dam will have no major impact on the surrounding area.

Construction of SP-II should be done as proposed in the proposal near to existing screening plant. As there is no other land is suitable for the project, alternatives has been not examined by NMDC Limited.

Executive Director

अधिशायी निदेशक

Executive Director

एनएमडीसी लि, दो.ली.अ.खा.

NMDC LTD, DIOM

हिन्दी में पत्रा व्यवहार को हम प्राथमिकता देते हैं। हिन्दी में पत्र व्यवहार का स्वागत है।

पंजीकृत कार्यालय : 10-03-311 / ए, खनिज भवन, कैसल हिल्स, मासाब टैंक, हैदराबाद - 500 028

Regd. Office : 10-03-311/A, Khanij Bhavan, Castle Hills, Masab Tank, HYDERABAD - 500 028