No.Ft.48-3996/2019 (FCA) 0 2 MAR 2020 EDS on Proposal No.FP/HP/VELEC/42317/2019

Diversion of 0.2646 ha of forest land in favour of HPESB Ltd for the construction of 33/11 KV2X1.6 MVA Un-manned sub station Raison at Ruagi Nala within the jurisdiction of Kullu Forest Division Distt Kullu, HP.

The following points are to be attended:

1. There is difference in estimated cost of the project mentioned against column No.A-1(vii) of online part-I and mentioned against column No.1(iii) in hard copy of part-I. In online part-I, 419 lac has been mentioned and hard copy 419.75 lacs has been mentioned. The estimated cost of the project should tally mentioned in hard copy and in online part-1.

2. Layout plan of the proposed project is also required to be uploaded against

additional information detail of part-I.

3. There is difference in employment likely to be generated, mentioned against column No.E in online part-I and given in hard copy of the proposal. Against column No.E(ii), '0' and against E(iii), '90', has been mentioned whereas in hard copy of part-I against column No.1(vi), '3 regular employment and 90 persons days' has been mentioned. The employment details given in online part-I and placed in hard copy should match. Necessary corrections are required to be made in the employment details mentioned in online as well as in hard copy of the proposal.

4. There is difference in legal status of forest land mentioned in online part-II and mentioned in the hard copy of the folder. In online part-II, Un-classed Forest has been mentioned and in hard copy of the proposal folder against column

7(v), in hard copy of part-II, UPF has been mentioned.

5. As per enumeration lists placed at P.Nos 45-46 of the proposal folder 5 trees and 8 saplings of different species are standing over the forest land proposed for diversion whereas against column No.4(ii), only 5 trees have been mentioned. All the trees including saplings are required to be mentioned against column No.4(ii).

6. Site inspection report of DFO uploaded/ placed in the proposal folder is not complete. All the columns of site inspection report have not been filled. Revised site inspection report of DFO duly filled is required to be uploaded/submitted.

Nodal Officer cum-AP CCF(FCA O/O Pr. CCF, H P. Shimla