FP/UK/Road/32572/2018

Date-06-04-2021

With reference to the EDS of RO,MOEFCC,GOI,Dated-31/12/2020, reply is received at your end via letter 3477/12-1, dated-18/03/2021, reply furnished for point no. 1 and 2 is not correct.

For Point No. 1 - Kindly furnish the justification from DFO via Site inspection report. Upload the report and send the hard copy to our office.

<u>For Point No.2-</u> Kindly provide 3 alternate for justifying your point and submit all necessary comparative chart and maps for the alternates.

.....NODAL OFFICE.....