SITE INSPECTION REPORT

Sr.	Items		Observations & Remark				
No.	Name of the D			SCI VALION	s & Kelliai	K	
1	Name of the Project & location (Range, Round, Beat)	:	: Full Title of the Project: Diversion				
	(range, riouna, beat)		0.170 2 Ha				
			Bridge at D	harivali vil	lage at Mar	ve road by	
			Brihanmumbai Municipal Corporation			ration	
			Range	Round	Beat	Village	
			Western	Andheri	Malvani	Aakse	
2	Name of the User Agency	:	Mumbai Brihanmur	l nbai Munic	ipal Corpo	ration	
3	Date of site inspection	1	10-02-202				
4	Extent (ha) & legal status of	:					
1	forest land proposed for		Reserved Forest- 0.1702Ha				
	diversion		1				
5	a) Detailed of forest land	:	As per Are	a Statemen	t attached	on nage	
3	proposed for diversion &	•	no. 59	a Statemen	it attacifcu	on page	
	activity-wise break-up of forest						
	land						
	b) Density & Eco-value class	:			Below 0.6		
			1 - 1	Eco-valu	e Class II		
6	Whether the requirement of	:					
	forest land as proposed by the		Yes				
	User Agency in col.2 part-1 is unavoidable & barest	12		•	103		
	minimum for the project. If no,						
	recommended area item wise						
	with details of alternative						
	examined.						
7	Whether the proposal involves	:		I	No		
	any construction of building						
	(including residential) or not?						
	If yes, details thereof	-			No		
8	a) Whether forest area	•		3 5 T			
	proposed for diversion is						
	important from wildlife point						
	of view or not	+			-		
	b) Details of any rare or						
	endangered or unique species						
	of flora & fauna found in						
	proposed forest land. IF so, the						
	details thereof						

	J
15	5)
7	"

	c) Aerial distance from the nearest boundary of any Protected Area (km)	:	Distance From Sanjay Gandhi National Park- 7.3 Km and Distance From Thane
	d) Remarks about sensitivity of the forest area likely to be	:	Creek Flamingo Sanctuary- 16.7 Km NA
	affected due to project e) Whether wildlife mitigation plan is required? If yes, reasons thereof		No
9.	Derails of Vegetation		
	a) Total number of trees to be felled	:	97
	b) Number of trees to be felled of girth below 60 cm.	:	86
	c) Number of trees to e felled of girth above 60 cm.	:	11
	d) Effect of removal of trees on the general ecosystem in the area	:	NA
10	Background note on the proposal (Short summary)		There is an existing bridge on creek near Dharivali village. The bridge lies near Madh-Aksa-Danapani beach. The existing bridge is narrow and cannot accommodate two big size vehicles at same time. Hence widening of this bridge is required for better plying of vehicles.
11.	Whether the proposal involves any violation of Forest (Conservation) Act 1980? If yes, a detail report on violation including action taken against the concerned officials to be	1	: No
12	Whether the proposal involved rehabilitation plan has been approved by the State Government?	d	: The proposal doesn't involve any rehabilitation hence no rehabilitation plan required.

14	Derailed on catchment & culturable common area under the project (if applicable) Utility of the project	:	NA There is an existing bridge on creek near Dharivali village. The bridge lies near Madh-Aksa-Danapani beach. The existing bridge is narrow and cannot accommodate two big size vehicles at same time. Hence widening of this bridge is required for better plying of vehicles.
15	Whether land being diverted has any socio-cultural/religious values? Whether any sacred grove or very old growth trees/forest exist in the areas proposed for diversion?	:	No
.16	Any other important information related to the project (Separate note may be attached, if req.)	•	
17	Details of documents & nhotographs enclosed.		Documents enclosed on page no. &
18	Recommendations of the Inspecting Officer (CCF/DCF/CF)		existing bridge to ensure smooth movement of vehicles on Madh Marve road. Hence the proposal is recommended as it is beneficial for the public.

Date: 28/10/2023 Place: Mumbai

Mumbai Manorous Conservalle Conservalle

(Adarsh Reddy)
Divisional Forest Officer
Mumbai Mangrove Conservation Unit

MAR