	Site Inspection Report Prescribed vide PCCF (HoFF) No.Desk-17-4/1445, Dated5/11/2015						
Sr.	Items	Observations and remarks					
No.	N. C.	Observations and remarks					
, 1	Name of the Project	Proposal for construction of Road at ODR-117 (Ambale)					
	and location (Range, Round, Beat)		di-Dhawaleshwa				
	Carl		total length - 0/0 no 11 6 2, 1198 a				indar
		Range- Sas		rea require	Ju 0.040)	114	
		_	Round- Saswad				
			Beat- Saswad				
2	Name of User Agency	Shri. Sanjay R Patil, Executive Engineer Pradhan Mantri					
3	Data of site inspection		k Yojana Depar	tment Pun	<u>e</u>		
4	Date of site inspection Extent (ha) and legal	0.84 ha.	0\ / 12 /2022				
	status of forest land	Reserve Fo	rest.				
	proposed for diversion	100017010	2001.				
5	a) Detail of forest	Name of	Item of	Forest La	and Requ	ired	
	land proposed	the	work/purpose	Survey/	Length	Area	
	for diversion	Village		Gat	&	Sq.m.	Ha.
	and activity-	A .	0 4 4 5	No. 1162 &	Width 700 X	8400	0.84
	wise break-up of forest land.	At- Amble	Construction Road	1198	12	0400	0.04
7 .	of forest failu.	Taluka-	Koau	1170	12		
	/	Purandar					
			required for th	e project	1	8400	0.84
1	7		•				
	b) Density and					.	
	Eco-value class		.01 and Eco-Va	lue Class-	-III, Opei	n Forest	•
6	Whether the	Yes.					
	requirement of forest	,	ž,				
	land as proposed by						•
	the User Agency in col.2 of Part-1 is						
	unavoidable and		*				
	barest minimum for						
	the project. If no,						
	recommended area						
_	item-wise details of						
	alternative examined.						
-	XX 71 .1 .1 1						
7	Whether the proposal						

_			
		involves any	No.
		construction of	
		building (including	
		residential) or not? If	
		yes details thereof.	
Ī	8	a) Whether forest	No.
١		area proposed	110.
-		for diversion is	·
		important from	
		wildlife point	
	,	of view or not.	No.
		b) Details of any	110.
		rare or	
		endangered or	
		unique species	
		of flora and	
		fauna found in	
		proposed forest	No.
		land. If so, the	
		details thereof.	
		c) Areal distance	Proposed area is not sensitive.
		from nearest	
		boundary of	
		any Protected	
		Area (km)	
		d) Remark about	
		sensitivity of	No.
		the forest area	110.
		likely to be	
		affected due to	
		project.	
		e) Whether	·
		wildlife	
		1	
		mitiSurveyion	,
		plan is	No.
		required? If	INO.
		yes, reasons	
		thereof.	·
	9	Details of vegetation:	7
		a) Total number	Zero.
		of trees to be	
		felled:	
		b) Number of	0.

	trees to be	
	felled of girth	
	below 60cm	0.
	c) Number of	
	trees to be	
	felled of girth	0.
	abow 60 cm:	
	d) Effect of	
	removal of	
	trees on the	
	general	·
	ecosystem in	
	the area.	
10	Background note on	Shri. Sanjay R Patil, Executive Engineer Pradhan Mantri
	the proposal (Short	Gram Sadak Yojana Department Pune of applied for use
	summary)	Construction Road of Forest Land to non-forest purpose
		i.e. the Reserve Forest Survey No/Gat No.1162,1198 of
		Village Amble Tal-Purandar, District Pune.
11	1 1	No.
	involves any violation	
	of Forest	
	(Conservation) Act	·
	1980? If yes, a detail	
	report of violation	
	including action taken	
	against the concerned	·
	officials to be	
	attached.	
12	Whether the proposal	No.
	involves rehabilitation	
	of displaced person. If	
	yes, whether	
	rehabilitation plan has	
	been approved by the	
	he State Government?	
13	Details of catchment	Not Applicable
	and cultivable	
	command area under	
	the project (if	
l	applicable)	
	Status of catchment	Not Applicable

	prevent siltation of reservoir (if	
	applicable)	
14	Utility of the project	Construction Road
15	Whether land being	No.
	diverted has any	
	socio-	
1	cultural/religious	1
	values? Whether any	
	sacred groves or very	
	old growth trees/	·
	forests exist in the	
	areas proposed for diversion?	
16		
16	Any other important information related to	No.
	project (Separate note	
-	may be attached, if	
	required)	
	required)	
17	Details of documents	Attached on page no.
	and photographs	,
	enclosed:	
18	Recommendation of	Recommended.
	the Inspecting officer	
	(DCF)	

(A.G.Bhong)

Sub Divisional Forest Officer, Bhor

Place :- Pune

Date :- 05 /12 / 2021

Site Inspection Photos



