

## SITE INSPECTION REPORT NOT BELOW THE RANK OF DCF

(For the forest land to be diverted under FCA)

A Proposal has been received by this office from **Construction Division (Building), PWD, Meerut** For diversion under (FCA-1980) of 84.600 ha. of Forest Land for Non-Forestry purpose. The Project envisages the use of forest land for **Construction of Choudhary Charan Singh Kavad Marg On RHS Side Shoulder of Upper Ganga Canal From Km Ch. 108.750 To Km Chainage 151.050 In District Meerut, Uttar Pradesh** The site inspection of the land involved in the proposal has done by me on dated- 16.04.2021.

On inspection of the site, it is found that the land required by the user agency is a Protect forest measuring – Area 84.600 ha. in Meerut District.

SL. No.	Name of Road	Length (In Km.)	Total Length (In Km.)	Width (In Mt.)	Area (In ha.)	
1	Upper (Main) Ganga Canal	108.750 to 151.050	42.300	20.00	84.6000	Protect Forest Land

The requirement of forest land as proposed by the user agency in col. 2 part -1 is unavoidable and is barest minimum required for the project.

Whether any rare/endangered/unique species of flora and fauna found in the area. If, so the details there of :- **NIL**

Whether any protected archaeological/heritage site/defence establishment or any other important monuments is located in the area, if so the details there of with NOC from competent authority, if required :- **NIL**

(a) The user agency has not violated the provisions of forest (Conservation), Act 1980 and no work has been started without proper sanction.:- **No violation under FCA.**


(b) It has been found that the user agency has violated the forest (Conservation), Act 1980 provisions. A detail report as per Para 1.9 of chapter 1, Para c of Handbook of forest (Conservation), Act 1980 is Attached:- **N.A.**

Specific recommendation for acceptance of otherwise of the proposal. :-

**Recommended for the acceptance of proposal.**

Place :- Meerut.

Date :- 08.07.2021

  
 (Rajesh Kumar)  
 Divisional Director  
 Social Forestry Division  
 Meerut.



Page 10

# SITE INSPECTION REPORT

The first part of the report is a general description of the site. This includes the location of the site, the type of land use, and the surrounding environment. The second part of the report is a detailed description of the site. This includes a description of the physical features of the site, such as the topography, the vegetation, and the water resources. The third part of the report is a description of the social and economic conditions of the site. This includes a description of the population, the level of education, and the level of economic development. The fourth part of the report is a description of the environmental problems of the site. This includes a description of the air pollution, the water pollution, and the soil pollution. The fifth part of the report is a description of the proposed remedial actions. This includes a description of the measures that will be taken to improve the environment and to protect the health of the population. The sixth part of the report is a description of the monitoring and evaluation program. This includes a description of the methods that will be used to monitor the progress of the remedial actions and to evaluate the effectiveness of the program. The seventh part of the report is a description of the conclusions and recommendations. This includes a description of the findings of the site inspection and the recommendations for further action.

