



JOINT INSEPECTION REPORT


Joint inspection of site for diversion of land for construction of Treatment units, storage tanks & Pump Houses for providing LWSS from Kashapat khad to Dansa via Pataina, Kuhl & Chiksa under the jurisdiction of Tehsil Rampur Bushahr, Distt. Shimla was done on **05-07-2014**.

Two possible alignments/sites were proposed by the user agency for construction of Treatment units, storage tanks & Pump Houses for providing LWSS from Kashapat khad to Dansa via Pataina, Kuhl & Chiksa, Both these sites comprises Govt./Forest land. Site No. 1 involve 0-97-31 hectare of Govt./Forest and no tree is involved for removal. In the site No. 2, 0-99-30 hectare of Govt./Forest land involved for diversion and no tree felling is required. Keeping in view of the minimum area and no felling of trees, Joint Inspection Committee is of the view that diversion of land coming in the site No. 1 involve less forest land and entails no felling of trees and there are Govt./forest land interspersed in both the alignments, there is no scope for avoidance of Govt./forest land and diversion of 0-97-31 ha. of Govt./forest is bare minimum and cannot be escaped.

The Joint Inspection Committee, therefore, recommends that the Govt./forest land measuring area 0-97-31 ha. coming in the alignment No. 1 as detailed in Check list-6 enclosed as Annexure-I be diverted under Forest (Conservation) Act, 1980 for construction of *L.W.S.S. from Kashapat khad to Dansa* Tehsil Rampur, Distt. Shimla.


Executive Engineer,
I&PH Division, Rampur.


Divisional Forest Officer,
Rampur Forest Division,
Rampur Bushahr.


Sub-Divisional Officer (Civil),
Rampur Bushahr, Distt. Shimla H.P.
Sub-Divisional Officer (Civil)
Rampur Bushahr