

JOINT -INSPECTION- REPORT

Joint inspection report of proposed construction of link road Reog, Dhawala Galanghati Km. 0/000 to 8/050. Comprising forest land in UPF/DPF Jadoon and UPF/DPF Dhawala Tehsil Kumarsain District Shimla H.P. Joint inspection of proposed alignment for construction of link road Reog Dhawala Galanghati Km. 0/000 to 8/050.

Sr. No	Particulars	First Alignment	Second Alignment	Third Alignment
01.	Length of road	8/050 Km.	9/000 Km.	9/600 Km.
02.	Length of road through Forest.	5/675 Km.	6/500 Km.	7/010 Km.
03.	Length of road through non forest land	2/375 Km.	2/500 Km.	2/590 Km.
04.	Forest land involved	05-79- 46 Hectare	06-45-00 Hectare	06-90-00 Hectare
05.	Name of Forest.	DPF & UPF Jadoon DPF & UPF Dawala	DPF & UPF Jadoon DPF & UPF Dawala	DPF & UPF Jadoon DPF & UPF Dawala
05.	No's of Trees Involved	86 No's	105 No's	150 No's


The above alignment has to necessary pass through forest area if the primary objective of linking the villages to the motor road is to be achieved. Hence there is no escape from using the forest land. Out of the above three alternative finalized for construction of road.

There is no violation under FCA 1980.

Dated:- 06.05.2024


Range Forest Officer,
Kotgarh Forest Range,
Kotgarh.


Divisional Forest Officer,
Division Kotgarh.


Assistant Engineer,
Thanedhar Sub- Division,
HP.PWD Thanedhar.


Executive Engineer,
Kumarsain Division,
HP.PWD Kumarsain.