

JOINT INSPECTION REPORT

Joint inspection report of site for the Construction of Pump House, sump well and main storage Tank etc. for Lift water supply Scheme "Taloty Khatol" Comprising Govt./Forest land Khasara No-500/1 in Mohal Deola 0-03-75 hecst. Khasara No. 717/1 in Mohal Taloty 0-00-35 hecst. in Tehsil Sunni Distt. Shimla HP

Joint Inspection of the proposed alignment C/O Construction of Pump House, sump well and Main Storage tank etc. was carried out by the undersigned officers on dated _____ and the observations are as under:-

Sr. No.	Khasara No.	Kind of land	Area in Hects.	Class of land as per forest record	No. of Trees	Remarks
1.	500/1	Un-Protected forest land.	0-03-75	Kawal Rubber 4-58 Deola	Nil	
2.	757/17/1	Un-Protected forest land	0-00-35	Forest land 4-58 Deola-	Nil	
TOTAL:-	2 Kita		0- 04-10 Hects.			

The above mentioned Construction of Pump House sump well at Deola, and Main Storage Tank 85000 ltrs cap. at Regnu covers under rural area.

There are no historical structures, natural water sources, Temples, Crimination ground, common path, public places etc. in the above said proposed area of these Structures.

Khans
Divisional Forest Officer,
Shimla Forest Division, HP.
Shimla Forest Division
Shimla - 171002 (HP)

4
Sub Divisional Officer (Rural)
Shimla Distt. Shimla HP.

Madani
Executive Engineer,
IPH Division Sunni

NCB
Range Forest Officer
Bhajji Forest Range
Sunl

(Signature)
Forest Block Officer
Khatol

(Signature)
जमीन अधीनस्थ अधिकारी (देवदारी)
देव देवला

(Signature)
A/E (C)

(Signature)
Sub Forest Officer
Sunl Distt./Shimla