

JOINT INSPECTION REPORT

Joint inspection report for the construction of Bus Stand at Taklech conducted on 25-03-2017, by the different departments under the Chairmanship of Naib-Tehsildar, Taklech.

In this regard, it is, submitted that the other department officers visited the site Khasra No. 593/1, measuring 00-16-66 Htsr., Siyarla Barshol to the construction of above Bus Stand.

Regional Manager, HRTC, Rampur has requested to sanction above land for the construction of Bus Stand.

It has been decided that there is no objection from different Departments.

The Joint Inspection committee therefore recommends that the land in Chak Siyarla Barshol of Govt. /forest land is to be diverted under forest Conservation Act, 1980 for construction of "Bus Stand Taklech".

*Jan*  
*AC*  
Executive Engineer,  
(B.R) HP. PWD Division  
Rampur Bushahr

*CB*  
*2/18*  
Executive Engineer,  
I&PH Division,  
Rampur Bushahr

*Shubh*  
Incharge 25/3/17  
HRTC, Rampur.

*G*  
*ASLL-29*  
Divisional Forest Officer,  
Rampur Forest Division,  
Rampur Forest Division H.P. Bahli Forest Range  
BAHLI

*S.S. Saini*  
Executive Engineer,  
(Elect) Division,  
Rampur Bushahr

*Naib*  
Naib-Tehsildar,  
Taklech

*Sub-Divisional Officer (Civil)*  
*Rampur Bushahr (H.P.)*