

## SITE INSPECTION REPORT


This is to certify that I have inspected the site proposed for establishing 1x10 MVA 110/11 KV Substation in Fsy.No.54a of Kansur village of Siddapur Taluk Uttara Kannada district in an extent of 1.33 ha. on 10-6-2019 along with Assistant Conservator of Forests Sirsi Sub Division Sirsi and Range Forest Officer Sirsi Range Sirsi and found that the proposed area comprises of acacia plantation, raised during the year 2006 to prevent encroachment by surrounding villages. The enumeration of trees coming within the site is completed and consists of 270 trees of *acacia auriculiformis* 29 trees of *Acacia mangium* and other natural trees like *syzigium cumini* (Neral) *Alseodaphne semicarpifolia* (Mase), *Careya arborea* (Kavalu), *Strychnos nux vomica* (Kasaraka), *Terminalia elliptica* (Matti), *Lagerstroemia lanceolata* (Nandi) *Mangifera indica* (Mavu), *Pterocarpus marsupium* (Honne), *Ficus recemosa* (Basari) and others.

The proposed area is surrounded by Kangod, Kansur Fsy.No. 54 on North, Betta Sy.No.36 on South Kangod, Kansur Fsy. No 54 on East and Kangod, Kansur Fsy. No 54 on west.

The site area is proposed for specific purpose and well intended to have components like approach road to substation (0.0195 ha.) 100m x 100m substation (1.00 ha.) and line corridor of 145m x 22m (0.32 ha.)

An extent of 1.33 ha. may be granted on lease to the user agency in the interest of public purpose.

Date: 10/06/2019  
Place: Sirsi

  
Basavaraj. V. Patil I.F.S  
Chief Conservator of Forests,  
Kanara Circle, Sirsi