

### SITE INSPECTION REPORT

1. Name of the proposal : Construction of Storm Water Pumping Station with approach access in Gazdarbandh, Village-Khardanda, Santacruz (W), Tal-Andheri, Dist- Mumbai Sub Urban
2. Forest Area involved : 0.2794 ha.
3. Location : Village-Khardanda, Santacruz (W), Tal-Andheri, Dist- Mumbai Sub Urban
- Division : Mumbai Mangrove Conservation Unit
- Range : Western Mumbai
- Round :
- Beat :
- Compartment No. : NA
- Coupe No. :
- Forest S.No. : D/1159 and D/1160 pt Village- Khardanda Tal-Andheri, Dist.- Mumbai surban, Maharashtra As per Area Statement on page No. 7
4. Date of site inspection : 22/2/2016
5. Details of Forest Type and flora and existing crop with botanical names : Mangrove species like *A. Marina*, of species is found at the project location
6. Details of fauna including their Population and distribution in sanctuary, National Park of Reserve : The project location is 10.2 km away from Sanjay Gandhi National Park.
7. Other aspects of importance : No
  - a) Historical/archaeological
  - b) Geographical
  - c) Religious
  - d) Geological
8. Remark regarding sensitivity of area likely to be affected due to project : The project area is surrounded by sparse mangroves. Proper care of the mangroves near project area during and after execution of the project is essential.
9. No. of Photographs ( If enclosed) : Nil.
10. Whether any work is violation of the Act has been noticed. : Nil

  
( Mr. Sanjay Mali )  
Divisional Forest Officer  
Mumbai Mangrove Conservation Unit