

SITE INSPECTION REPORT

1	Name of the project	Khurda Road Bolangir New B.G. Rail link Project Phase IV i.e. from Km 180-238
2	Name of the district /division.	Boudh/ Boudh Forest Division
3	Date of inspection	21.12.2018 & 22.12.2018
4	Name & designation of the inspecting officer	<ol style="list-style-type: none"> 1. Sri Jashabanta Sethi, D.F.O 2. Sri Narayan Swain, I/c FRO, Purunakatak 3. Sri Bipin Bihari Routrai, FRO, Boudh 4. Sri Saroj Kumar Mishra, FRO, Manamunda 5. Sri Radheshyam Kampa, Fr. Purunakatak 6. Sri Sushil Kumar Hota, Fr. Boudh 7. Sri Ajit Kumar Acharya, Fr. Manamunda 8. Sri Sunil Kumar Pradhan, Fg. 9. Sri Sushanta Kumar Sahu, Fg. 10. Sri Ranjit Kumar Pradhan, Fg. 11. Sri Deepak Kumar Nayak, Fg. 12. Sri Sunil Kumar Majhi, Fg. 13. Sri Pradeep Kumar Sahu, Fg. 14. Jyoti Ranjan Barik, Fg. 15. Deepak Kumar Pradhan, Fg.
5	Name & designation of the other officer who attended the inspection including representative of the user agency.	<ol style="list-style-type: none"> 1. Sri M.V Satyanarayan Mishra, Dy.CE 2. Sri S.P Mishra, Asst. Ex Er., Bolangir 3. Sri B.K Pradhan, SSE (Work) Cons/Bolangir 4. Smt Babita Dalabehera, Tahasildar Harabhanga 5. Sri Lalatendu Si, Tahasildar Boudh 6. Sri Nishikanta Meher, R.I 7. Sri Hammid Kumar Mahalik, RI 8. Sri Biplab Mandal, Sr. Surveyor 9. Sri Naba Kumar De, Sr. Surveyor
6	Legal status of forest land with area proposed for diversion	Revenue Forest Land
7	If area required for diversion has been demarcated on the ground.	Demarcation completed.

8	Item wise breakup of the forest land proposed for diversion	Purpose	Revenue Forest	Total
		Diversion of 13.218 Ha. of Forest land in connection with Khurda Road to Bolangir New BG Rail Link Project	Lunibahal	0.061
			Bhubaneswar	3.921
			Rambhikata	1.048
			Nuapada	0.328
			Bandhapathar	0.096
			Jogibhogara	0.057
			Khamaripada	0.162
			Sorisanali	0.077
			Jadapal	0.049
			Pingalabeda	0.182
			Balakira	0.688
			Gopinathpur	0.223
			Jharmunda	0.599
			Chhelibahal	0.801
			Kirasira Jungle	3.225
			Landibandha	0.809
			Bahajor	0.02
			Sanadunguripali	0.589
			Kirkichipali	0.283
	Grand Total	13.218 ha.		
9	Condition of vegetation and type of forest applied area.	Very few growths of Babul, Palas, Mahua, Kendu, Khajuri, Rohini, Jamu & Neem trees are found in some patches. Encroachment noticed in some patches, for paddy cultivation.		
10	Position of wild life in general	No.		
11	Whether the applied area is involved with any eco-sensitive area/ national park/sanctuary.	No		
12	No. of tree to be felled and its impact on the eco-systems.	128 trees has been marked and the User agency submitted tree enumeration list. Also User Agency undertakes that they will pay the CA amount as required.		
13	Details of broken up area and reclamation done if any.	Nil		

14	Position of displacement of people and adequacy of rehabilitation if any.	FRA Certificate submitted.
15	Position of rare and endangered species available of importance of area from eco-social point of view.	No.
16	Area selected for diversion if included in the D.L.C report or not.	Yes. Total diverted forest land is involved in DLC report.
17	Suitability of the identified non forest area for compensatory Afforestation.	Yes. 26.44 ha. degraded Forest land identified in Subarnagiri RF Compt. No. 1 of Boudh Range under Boudh Forest Division & 13.26Ha. degraded revenue forest kissam land in Balakira village of Mundapada R.I Circle bearing Khata No. 287 & Plot. No. 1372 & 1374 of Boudh Tahasil of Boudh Dist.
18	Violation of forest (conservation) Act 1980 if any and action taken thereof.	No.


08/11/20

Divisional Forest Officer
Boudh Division
Boudh Division