

JOINT INSPECTION REPORT

Joint inspection report of the proposed/planned road from Shamshar to Chalohan km 0/000 to 3/420 in Tehsil Anni Distt. Kullu H.P.

Certified that the joint inspection of the road from Shamshar to Chalohan km 0/000 to 3/420 has been conducted on dated:- **19/09/2020** by the committee of following officers.

Divisional Forest Officer,
Anni Forest Division,
Luhri Distt. Kullu

Executive Magistrate,
Sub-Tehsil, Anni Distt. Kullu H.P.

Executive Engineer
Outer Seraj Division
HPPWD Nirmand

It is certified that every possibility has been explored for alternative alignment and it has been considered that the proposed alignment is final and alternative alignment has been rejected in favour of the proposed alignment. It is also certified that -- 75 trees are coming the proposed alignment. The Alternative alignment rejected due to following reasons.

Proposed alignment				Alternative alignment			
No. of trees	Forest land involved in km	Forest land involved in Hec.	Other reason	No. of trees	Forest land involved in km	Forest land involved in Hec.	Other reasons
75	2.380km Dumping = Total =	1.428 ha. 0.24 ha 1.668 ha	Switable and Feasible	97	2.645 km dumping Total	1.587 ha 0.24 ha 1.82 ha	Increased Area of forest land & more numbers of trees
				101	3.050 km dumping Total =	1.83 ha 0.24 ha 2.07 ha	Increased Area of forest land & more numbers of trees

There are no Civil/Defence structures protected archeological / heritage site other Govt. property and other important monuments which will be effected due to this project. No families are being displaced due to this project and rehabilitation plan is prepared accordingly (if applicable)

Executive Engineer
Outer Seraj Division
HPPWD Nirmand

Executive Magistrate,
Sub-Tehsil, Anni.
Distt. Kullu H.P.

Divisional Forest Officer
Anni Forest Division
Luhri Distt. Kullu

ASSISTANT ENGINEER
ANNI SUB-DIVISION
ANNI DISTT. KULLU (H.P.)

Visheshwar
4/10/2020

Bohnanag