FORMAT OF JOINT INSPECTION REPORT FOR FOREST CONSERVATION ACT 1980

JOINT INSPECTION REPORT

	Construction of 3 Nos. of water tank out of which two Nos which fall within Andheri R.F. are reservoir tank a	nd
 Name of the project : 	Construction of 3 Nos. of water tank out of which two Nos which fail within Andrew tank are reserved	
	one is distribution tank which falls within private holding under Singtam (T) Range.	
	one is distribution tank which falls within private notating under singlain (1) range.	. 10

- 2. A brief of project : Construction of water tank at Andheri R.F. and laying of pipe line is to meet up the acute demand of water by the public residing at Shantinagar, Singtam, East Sikkim. There are 48-50 houses.
- 3. Date of Joint survey: 21.08.15
- Participants: Name
 Designation
 Mohan Kr. Subba, F.G. and F.G. Saraswati Gautam
 Santosh Kalden (Tamang) A.E. BAC, Khamdong
 - Department Forest Env. & W.L. Mgt. Department/RM & DD
- 5. Details of land : Andheri R.F. (1):8'8''x8'' = 70.40 sft. for reservoir tank (2) 14'6''x7'9'' = 115.34 sft. for reservoir tank
 - - Total = 5888.74 sft.
- 6. Legal status of Forest land : Andheri Reserve Forest

 Any other

 6'x3"= 18.00 sft. Private land

Item wise breakup of Forest land required:

1st Tank-

E- 27° 14′ 18′7″

8'8"x8'

= 70.40 sft. for reservoir tank

N- 88° 30′22.6"

2nd Tank - E- 27° 14′ 16′7″

160 ft +1741 ft.= 1901 ft.x3'

Total forest land to be required

N- 88° 30′22.1″

14'6"x 7'9"

= 155.34 sft. for reservoir tank

= 185.74 sft.

= 5703 sft. (1½"pipe line to be laid)

= 5888.74 sft.

8. Wildlife Area/National Park Sanctuaries:

No.

9. Types of Vegetation/Felling of trees involved or not :-

No trees are involved except ground vegetation like banmara, nettle, titay

10. Certificate of DFO (T) concerned if tree felling is not involved : -

-No-

11.A Brief about Topography, Soil Forest Environment and Wildlife: Black soil. The area is a small plot of land which is covered

Khamo .g, East Sikkim

by small bushes and grasses & occasional spotting of fox, squirrel, monkey.

11.A brief observation of team and its recommendations:

Since the water source is in Andheri R.F. i.e. perennial water source above applied area of the tank. The water Is to meet up the acute problem of the public residing at Shantinagar about 48-50 houses

are there. There is no other water source other than this.

-No-

12. Any other aspect related to project and Forest area:

Santosh Kalden (Tamang)

A.E. BAC, Khamdong

Pawan Subba. Range Officer,

Singtam (T) Range.

RANGE OFFICER Singtam (Y) Rayne

SECRETARY

Rural Management & Dev. Deptt. Govt. of Sikkim, Gangtok