

JOINT INSPECTION REPORT


1. Village and Survey Number : Village –Vashi Tal Thane Dist.Thane
Village- Turbhe Tal Kurla Dist-Mumbai
Suburban.
2. F.S./Coupe Number : NA
3. The four boundaries of the forest area demanded. : As per area statement attached on page---
4. The area has/does not have tree growth : The area at some place has mangrove covered.
5. If yes what is its density : Average density is 0.7 to 0.9
6. It is certified that no work has been started :
 - i) On Non-Forest Area : No work has been started on Non-Forest Land.
 - ii) On Forest Area : No work has been started on Forest Land.
7. It is also certified that the forest area actually required for the project has been demarcated on the ground : Yes, the forest area required for the project has been demarcated on the ground.
8. Actual Forest Area required for Completion of the project work : 1.4074 Ha.
9. Date of Joint Inspection : 13 / 10 / 2018

It is agreed that the forest area mentioned above is found correct on the spot and on map.



(Rahul Giribuwa)

Exe. Engineer,MSRDC, Mumbai



(M.B. Ghodke)

Assistant Conservator of Forests,
Mangrove Protection Mumbai

Date :- 13 / 10 / 2018

Place :- Mumbai