

JOINT INSPECTION REPORT

Joint inspection report of the proposed/planned road from Shamsher to Panei km 0/000 to 9/150 in Tehsil Anni Distt. Kullu H.P.

Certified that the joint inspection of the road from Shamsher to Panei km 0/000 to 9/150 has been conducted on dated-06.09.2018 by the following officers.

Range Forest Officer,
Forest Range Chowai
Tehsil Anni, Distt. Kullu

Executive Magistrate,
Sub-Tehsil, Anni Distt. Kullu H.P.

Assistant Engineer
Anni Sub-Division
HPPWD Anni

It is certified that every possibility has been explored for alternative alignment and it has been considered that the proposed alignment is final and alternative alignment has been rejected in favour of the proposed alignment. It is also certified that -- 615 trees are coming the proposed alignment. The Alternative alignment rejected due to following reasons.

Proposed alignment				Alternative alignment			
No. of trees	Forest land involved in km	Forest land involved in Hac.	Other reason	No. of trees	Forest land involved in km	Forest land involved in Hac.	Other reason
615	6.965 Dumping Total	4.18 Hec 1.13 Hec 5.31 Hec	Subtable & feasible	720	8.580 Dumping Total	5.15 1.13 6.28 Hec	Increased length in forest land & more number trees involved

There are no Civil/Defence structures protected archeological/heritage site other Govt. Property and other important monuments which will be effected due to this project. No families are being displaced due to this project and rehabilitation plan is prepared accordingly (if applicable)

Range Forest Officer,
Forest Range Chowai
Tehsil Anni, Distt. Kullu

Executive Magistrate,
Sub-Tehsil, Anni HP
Distt. Kullu H.P.

Assistant Engineer
Anni Sub-Division
HPPWD Anni

Executive Engineer
Outer Seraj Division
H.P.W.D. Nirmal

Shamsher Singh,
Rd. Panei

Divisional Forest Officer,
Anni Forest Divn at Lohri

Sub Divisional Officer (C)
Anni Distt. Kullu H.P.