## Joint Inspection for Construction of read from Dhar to Dhangar via Lunsu Km 0/0 to 6/500 was carried out by Committee Chaired by Sub Divisional Officer (Civil), Dehra, District Kangra on 16.03.2017

1	Name of the Circle	Hamirpur
	District	Kangra
**	Division	Dehra
	Sub-Tehsil	Haripur
	Forest Range	Dehra
2.	Name of the road	C/O Dhar to Dhangar via Lunsu road Km 0/0 to 6/500
3.	Total length of the road for which forest land	In forest land: 5103 m (in full width)
	has already been broken / constructed passing	Area Violated : 3.0616 ha
	through the forest area and the private area.	In Pvt. Land : 1397 m (in full width)
4.	Length of road and extent (in hectare) Passing	5103 m (in full width) : 3.0616 ha
	through forest	Dumping Site 2 Nos. : 0.1564 ha
		Total: 3.2180 ha
1	Dates of starting & completing the work	Not Known
6.	Name of organization which constructed the road.	Not Known
7.	Details of the damages caused to bio-diversity including number of trees felled other than breaking the earth (which is covered under point 5 above).	As the construction is done long back, so no damages caused to the bio-diversity at present.
8.	Detail of the soil conservation / engineering works necessary on the upeer and lower sides of the road	Protection work to be constructed by HPPWD  C/o R/walls and B/walls : 260 m Nos. Rs. 29.50 Lacs  Total : Rs. 29.50 Lacs
9.	Estimate expenditure for carrying out these engineering works	Rs. 29.50 Lacs
10.	Recommendation of the Committee	Strongly recommended as this road will provide facility to Dhar, Dhangar, Lunsoo villages and Govt. High School Lunsoo with total population of 5000 souls. In addition to this, it will also provide facility to forest official to cover inspections as well as to extract forest produce as and when available in the area.

S.DK

5.2.0(c.

Divisional Forest Officer Dehra, District Kangra (HP) (Member)

Klheba Sub Division Officer (CWI) (Chairman) Dehra, anticet Kangra (HP)

District Kangra (HP) (Member Secretary)