

(4)

JOINT INSPECTION REPORT**1. Village and Survey Number**

Forest Land Required								Non-Forest Land Required		
Bridge Name	Name of Village	Sr. No/ CTS No	Length (M)	Width (M)	Total Area in Sq. M	Total Area in Ha	Legal Status	Sr. No/ Cts No.	Total Area in Sq. M	Total Area in Ha
Construction of Bridge	Aakse	Survey No. 16 CTS 99 Pt	62	27.45	1702	0.1702	Reserved Forest	11 Pt	2180.67	0.2181
								16 Pt	2338.16	0.2338
								Khadi	181.66	0.0182
								Road	2178.51	0.2179
Total					1702	0.1702			6879	0.6879

2	F.S./Coupe Number	NA
3	The four boundaries of the forest Area demanded	NA
4	The area has/does not have tree growth	Yes Mangroves Tree Present on the Site
5	If yes what is its density	0.6
6	It is certified that work has been started	
	i) On Non-Forest Area	Not Started
	ii) On Forest Area	Not Started
7	It is also certified that the forest area actually required for the project has been demarcated on the ground.	Yes, the forest area required for the project has been demarcated on the ground.
8	Actual Forest Area required for Completion of the project work	0.1702Ha
9	Date of Joint Inspection	01/12/2021

It is agreed that the forest area mentioned above is found correct on the spot and on map

**Executive Engineer (Bridges) WS
Brihanmumbai Municipal Corporation**

**Assistant Conservator of Forests
Mumbai Mangrove Protection Unit**

Date: 24 / 08 / 2023
Place: - Mumbai