

JOINT INSPECTION REPORT

1. Village and Survey Number

Forest Land Required							Non-Forest Land Required			
Component	Name of Village	Sr. No/ Gut No.	Length (M)	Width (M)	Total Area in Sq. M	Total Area in Ha	Legal Status	Sr. No/ Gut No. CTS No.	Total Area in Sq. M	Total Area in Ha
Construction of Railway Line	Dahisar	Un-surveyed Railway Land	874	42	36878.89	3.6879	Un-notified Mangrove Forest (Railway land)	Un-surveyed Railway Land	10816.56	1.0817
Construction of Railway Line	Penpada	Un-surveyed Railway Land	594	24	14274.35	1.4274	Un-notified Mangrove Forest (Railway land)	Un-surveyed Railway Land	14151.22	1.4151
					Total	5.1153		Total		2.4968

2	F.S./Coupe Number	NA
3	The four boundaries of the forest Area demanded	NA
4	The area has/does not have tree growth	Yes Mangroves Trees Present on the Site

106 A

5	If yes what is its density	0.6
6	It is certified that work has been started	
	i) On Non-Forest Area	Not Started
	ii) On Forest Area	Not Started
7	It is also certified that the forest area actually required for the project has been demarcated on the ground.	Yes, the forest area required for the project has been demarcated on the ground.
8	Actual Forest Area required for Completion of the project work	5.1153 Ha
9	Date of Joint Inspection	17/03/2022
It is agreed that the forest area mentioned above is found correct on the spot and on map.		
 (H.N. Yadav) Assistant Engineer Mumbai Railway Vikas Corporation Ltd.  Assistant Conservator of Forest Mumbai Mangrove Protection Unit		



Date: - 17/03/2022
Place: - Mumbai