


SITE INSPECTION REPORT

I have inspected the site of 0.2219 ha. Area proposed for laying of Zip Line with walking path and construction of Base Structure in Chamundibetta RF, in favour of the Deputy Director, Department of Tourism, Mysore in Chamundi betta village of Mysuru Taluk, Mysuru district on 13.03.2019.



Deputy Conservator of Forests,
Mysuru Division, Mysuru