

### PART-III

(To be filled by the concerned Special Principal Chief Conservator of Forests)

14. Whether site, where the forest land involved is located has been inspected by concerned Special Principal Chief Conservator of Forests (Yes/No). If yes, the date of inspection & observations made in form of inspection note to be enclosed.

Yes.

The Site inspection has been carried out on 05.04.2018 and the detailed report of site inspection is enclosed

15. Whether the concerned Special Principal Chief Conservator of Forests agree with the information given in Part- II and the recommendations of Deputy Conservator of Forests.

Yes.

Agree with the recommendation of Deputy Conservator of Forests.

16. Specific recommendation of concerned Conservator of Forests for acceptance or otherwise of the proposal with detailed reasons.

The submergence area caused by the dam (having axis between 25°40'0.109" N 92°46'54.822" E and 25°39'56.920" N 92°46'50.448"E) was projected to be altogether 45.28 ha comprising of Charchim DCRF 32.64 ha and Phanglangso USF 12.64 ha in total of Hamren Forest Division. On visiting the area and close study of the toposheet map 83C/14, this agrees approximately well taking the highest feature of the land under submergence. This is on the side of Hamren district in the Charchim DCRF under the control Karbi Anglong West forest division. It is seen that ecological evaluation of the water body was not carried out. Therefore, it is suggested that a minimum cess of Re. 1/kWh to be charged then be increased by factor after the financial recovery period which stands at IRR 6.6. Otherwise there is no objection to the project.

Date: 06.04.2018

Place: Diphu

Signature :

Name :

Official Seal :

