

### JOINT INSPECTION REPORT

Sl no.	Particulars	Report
1	Name of project	Proposed construction of 60m span steel bridge over Thulong/Rungpee Kyung along Bay-Pentong road at upper Dzongu, North Sikkim by Road & Bridges Department.
2	Area of Project	BAY - THULUNG RUNGPEE KYUNG, UPPER Dzongu.
3	GPS Co-ordinates	a) N27°30'51.62" E88°26'21.70" b) N27°34'51.13" E88°20'21.74"
4	Date of joint inspection	Dated. 29/02/2016
5	Participants Name Designation Department	Land Revenue, Forest and user agency Roads & Bridges and Panchayats.
6	Detail of Land (in ha) a) Private Land b) Forest Land c) Total Land involved	Forest Land(Khasmal) = 0.0300 ha.
7	Legal status of forest land: a) Gaucharan b) Khasmal c) Reserve forest d) Any other.	Khasmal
8	Item wise break up of forest and required as per project.	Enclosed.

9	Whether any National Park, wildlife sanctuary involve.	No.
10	Enumeration list of forest crops	Enclosed.
11	Density of crops in %	
12	Legal status of private land as per 1951-52 survey record.	As per 1977-78 survey record.
13	Type of vegetation:- a) Top canopy b) Middle canopy c) Ground Flora	Nil
14	No. Of felling of trees/poles and other forest produce involved or not if yes indicate details.	Enclosed.
15	Brief observation of inspection team.	The proposed project construction of bridge will connect Bay to Pentong village as it benefits the local people in transportation and other income generating schemes.

Assistant Conservator of Forest  
Mangan Sub Division  
North Territorial Division  
Forest & Environment Department

User Agency

JUNIOR ENGINEER  
Road and Bridges  
Mangan S.D. W.D.

Land Revenue Department.

CHIEF ENGINEER: MAGISTRALE  
Dzongu Sub-Division  
North Sikkim

Divisional Forest Officer  
North Territorial Division  
Forest & Environment Department

Forest Department.

Norden Z. Bhutia  
Range Officer  
Dzongu (T) Range  
Forest Env. & W/L M. Dept.